



KEEP OUT  
DANGER

The DeHANEY Round BARN

AURORA, COLORADO

Art Hutchinson, Photographer

JANUARY, 1988

Negative, Aurora History Center

View - West side of BARN - entrance.

Photo #1



The DELANEY Round Barn

Aurora, Colorado

Art Hutchison, Photographer

JANUARY, 1938

Negative - Aurora History Center

View - North side of Barn

Photo # 2



The DELANEY Round BARN

AURORA, COLORADO

Art Hutchinison, Photographer

JANUARY, 1988

NEGATIVE; - AURORA HISTORY CENTER

View - Detail of windows on S.W. side of BARN. Note GALVANIZED steel panels  
below the windows.

Photo #3



The DELANEY Round Barn

AURORA, COLORADO

Art Hutchinson - Photographer

JANUARY, 1988

Negative - AURORA HISTORY CENTER

VIEW - Looking south towards barn from bank of West Tollgate Creek. Note DAM behind barn AND young trees which have grown up in now empty RESERVOIR.

Photo # 4





The DELANEY Round BARN.

AURORA, COLORADO

Art Hutchison, Photographer

JANUARY, 1998

Negative - AURORA History Center

View - East Side of BARN - NOTE SAG ABOVE DOORWAY WHERE THE ORIGINAL  
SPANNING WAS BOARDED UP.

Photo # 5



THE DELANEY BARN

AURORA, COLORADO


ART HUTCHINSON - PHOTOGRAPHER

JANUARY 1988

NEGATIVE - AURORA HISTORY CENTER

VIEW - DETAIL OF ROOF INTERIOR

PHOTO #6



# The DELANEY BARN

AURORA, COLORADO.

Art Hutchinson - Photographer

JANUARY, 1988

Negative - Aurora History Center

VIEW - DETAIL OF RAFTERS

DETAIL OF REPAIR OF WOODPECKER HOLE BY SMALL METAL PLATE.

PHOTO # 7