101-11 AHC1985-2 Page 1 of 3 pages

KENTUCKY HISTORIC RESOURCES Individual Inventory Form

Mason County

I. Name of Resource:	16. Date:
Springhouse on Flat Fork	Original Building early 19th C. [8
2. Original Owner:	Addition
Not Known	17. Style:
3. Other Names:	Settlement Vernacular [2V
4. Prehistoric Site Building X Object	18. Architect/Builder:
Historic Site Structure Other	Not Known
5. Location: west side of Kentucky 161, 1 2/1	0 19. No. of Stories: Two [2.0
miles south of Kentucky 324, nea	20. Original Floor Plan:
Mays lick	Rec. Single Cell [1R
6. Owner's Name:	21. Single Pile X Double Pile N.A. X
Cocil McConthy	22. Roof Form & Material: Original
Cecil McCarthy	
7. Owner's Address:	23. Structural Material:
Flat Fork Pike	Stone [S
Mays Lick, Kentucky 41055	24. Exterior Material: Stone [S
8. Evaluation: [G] [
9. Recognition & Date:	25. Foundation MaterialStone S
Nat.Landmark Local Landmark	50012 [
Nat.Register HABS/HAER	26. Major Alterations: None X
Highway Marker KY Inventory X	Moved/Rebuilt Other
KY Landmark Certificate	Additions
10. N.R.Status & Date:	27. Special Features:
11. N.R.Group:	Spring arises outside Springhouse
District Name: [28. Outbuildings:
Mult.Resource Area:] House, Quarters, Three Barns [5
Thematic Name: Early Stone Buildings[] 29. Original Function:
12. Historical Theme:	Springhouse 01C
Primary: Architecture [030	30. Present Use:
Secondary:] Springhouse (01C
Other: [] 31. Condition:
13. Statement of Significance:	Excellent [E
~	32. Endangered: Yes

[]

33. Attach Photos:

Roll: 24

Excellent example stone springhouse; type unique to Mason County.

14. History:

Not Researched.

SL: 1987

No

Photo Nos23-36 No. of Slides: X

15. Source of	historical	information	and/or	contact	
person:					

34.	Prepared by:	Carolyn Murray-Wooley
35.	Organization:	Kentucky Heritage Council
	Date:	
37.	New Survey	April 1984 X Resurve

KENTUCKY HISTORIC RESOURCES INVENTORY

36.	UTM Point of Primary Building: 3	7. USGS Quadrant:	38. G.I.S. Mod.
		linsville	39. Coordinate Accuracy []
40.	UTM Points of Boundary:	0	
	1 1 153 NED 4214 740 C. 1	1 253 925 4264 180	E. 172531004264760
	B. 17 253 600 4264 250 D. 1	7253060 4264 330	F
	Total Acreage in Present Property:	. 42. Acreage In	uded in Nominated Boundary: 60
43.	Site Plan and Boundary Description	and Justification:	
	E A	Arte enclosed.	he a B. C. D. E as thrown.
N		B-C is an Flat J	orte D. E is at they 161
Λ		Boundary inclu	des Apring bouse pont,
	birg da lancar rosa aid	house quarter	e and 3. barac.
	Apring	7 contributing	building.
	quality the	1 Contrebution	percelure (fond)
	X KI KILL	1 hon contrell	ating building (gorage)
	I Igarage	Dounda	regincludes a portion
	berne D	ALL ATERIA	et form which can Leen from house.
1		1 use any	Irom house .
		B Hal Fork.	acto parto
			_
		-	
		-	~ .
	#		

45. Description and House Plan

One-room, dry-stone springhouse, ca. 14 x 16 feet; two stories tall, doorway to each story in north end of house; north gable end of roof extended to roof over entrance. Spring flows through rock lining into circular basin outside northwest corner of house; basin ca. four feet tall, covered by stone slab. Pool overflows and goes under entrance walk and under stone door threshold into springhouse. Steps descend from west hillside to walkway between spring and springhouse. Springs flows out southeast corner of springhouse into stone lined pond.

The spring is located downhill, east of the house.

There are several other original buildings on this farm complex. The main house is a two-story, three-bay weatherboarded house with a two-story ell. Two two-story weatherboarded servants' quarters are in the yard, southeast of the house. There are three barns around the barn yard south of the house. All of these are in good condition.

Addendum: The entire complex was an early pioneer farmstead, the house dating to the early 19th century, the quarters and barns to mid-19th century. The garage is non-contributing. The complex is a good illustration of the relationship of various domestic and agricultural buildings on a pioneer farm. The springhouse is an extremely significant example.

____ rages

IND I SPRINGHOUSE ON FLAT FORK 13.13 11051 16 H rock pene spring The wall sprin Ala Som sin threshold to spring house, spring flows under it. lina vaicia doorway also coarra ky stone slabs spanning spring read.

0 ND

4 1987

SEP