



SCHINDHELM-DREWS HOUSE

JOHNSON COUNTY, IOWA

MARYBETH SLONNEUER - photographer & holder
of negative

1991

FRONT FACADE (WEST) - UNRESTORED VIEW

#1



SCHINDHELM-DREWS HOUSE

JOHNSON COUNTY, IOWA

MARYBETH SLONNIGER - photographer & holder
of negative

1991

1880'S ADDITION SHOWING FRONT FACADE (SOUTH)
& SIDE ELEVATION (EAST) - UNRESTORED VIEW

2



SCHINDHELM-DREWS HOUSE

JOHNSON COUNTY, IOWA

MARYBETH SLONNEGER - photographer & holder
of negative

1991

VIEW FROM ALLEY (NORTH BOUNDARY OF PROPERTY)
SHOWING EAST & NORTH ELEVATIONS OF 1880S
ADDITION, LEAN-TOS & NORTH END OF STONE
HOUSE - UNRESTORED VIEW

3



SCHINDHELM-DREWS HOUSE

JOHNSON COUNTY, IOWA

MARYBETH SLONNEUER - photographer & holder
of negative

1992

WORK IN PROGRESS VIEW - FRONT FACADE (WEST)

OF STONE HOUSE W/ EXPOSED LIMESTONE
WALLS & REBUILT CHIMNEY

#4



SCHINDHELM-DREWS HOUSE

JOHNSON COUNTY, IOWA

MARYBETH SWONNEGER, photographer & holder
of negative

1992

WORK IN PROGRESS VIEW - VIEW FROM ALLEY
W/ EXPOSED CLAPBOARD OF EAST & NORTH
ELEVATIONS OF FRAME ADDITION, SHOWING
REMOVAL OF LEAN-TOS & EAST FACADE OF
STONE HOUSE

#5



SCHINDHELM-DREWS HOUSE

JOHNSON COUNTY, IOWA

MARY BETH SLONNEUER, photographer & holder
of negative

1992

WORK IN PROGRESS VIEW - WEST & SOUTH
FACADES OF 1880S ADDITION

#6



SCHINDHELM-DREWS HOUSE
JOHNSON COUNTY, IOWA

MARYBETH SLONNEKER-
photographer & holder of negative

1992

WORK IN PROGRESS VIEW OF
INTERIOR OF NORTH ROOM
IN THE STONE HOUSE (WALLS
IN UNRESTORED CONDITION;
SUB-FLOORING INSTALLED).

#7