


5/28/76 NPS Number Title: 0 Ku Loc.



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM



SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

AND/OR COMMON

DOMINGUEZ RANCH ADOBE

Rancho San Pedro Dominguez Ranch Homesite

| 2 LOCATI | ON 18127 | South Alameda | L | | |
|-----------------------|----------------|---------------|-----------------------|---------------------|-------|
| CITY, TOWN Compton | | VICINITY OF | COUNTY Los Angeles | STATE California | 90220 |
| 3 PHOTO | REFERENCE | | | | - |
| PHOTO CREDIT | Harold Sanders | | DATE OF PHOTO | August 1975 | > |

NEGATIVE FILED AT Del Amo Photography Torrance, California

IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

West view of original rear, now facade


PHOTO NO

INT: 2983-75



> UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM



SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

DOMINGUEZ RANCH ADOBE AND/OR COMMON Rancho San Pedro Dominguez Ranch Homesite LOCATION 18127 South Alameda CITY, TOWN VICINITY OF COUNTY California 90220 Los Angeles Compton **PHOTO REFERENCE** August 1975 Harold Sanders PHOTO CREDIT DATE OF PHOTO Del Amo Photography NEGATIVE FILED AT Torrance, California **IDENTIFICATION** DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET PHOTO NO

Interior, restored kitchen



> UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

| RECEIVED | MAR | 3 | 197 | 6 | |
|----------|-----|----|-----|--------|---|
| | | MA | Y 2 | 8 1976 | 5 |


| | SEE | | N HOW TO COMPL ALL ENTRIES EN | | | | 1 |
|---|---|----------------------------------|----------------------------------|----------|-------------------|---------------------|-------|
| 1 | NAME | | | | | | |
| | HISTORIC | DOMIN | GUEZ RANCH ADOBE | C | | | ÷ |
| | AND/OR COMMON | Rancho San Ped | ro Dominguez Ra | unch Hom | esite | | |
| 2 | LOCATION | J 18127 | South Alameda | | | | |
| | CITY, TOWN Compton | | VICINITY OF | Los | COUNTY Angeles | STATE California | 90220 |
| 3 | 3 PHOTO REFERENCE PHOTO CREDIT Harold Sanders | | | | DATE OF PHOTO | August 1975 | |
| | NEGATIVE FILED AT | Del Amo Photog Torrance, Cali | | | | | |
| 4 | IDENTIFIC | ATION | | | | | 1 |
| | DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET | | | | | PHOTO NO | + 4/5 |

Interior, bedroom



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM



| | SEE | INSTRUC | TION TYP | S IN HO PE ALL | OW TO COM ENTRIES IE | PLETE | NATIONAL REGIST SE WITH PHOTOGR | ER FORMS | |
|-------------------|---|---------------------|-------------|-------------------|-------------------------|-------------|------------------------------------|--|-------|
| 1 | NAME | | | | | | | | |
| | HISTORIC | | | | | | | | |
| 1 | DOMINGUEZ RANCH ADOBE | | | | | | | | |
| - | AND/OR COMMON | Rancho | San | Pedro | Dominguez | Ranch | Homesite | ······································ | |
| 2 | LOCATION | Ĩ | 181 | 27 Sou | th Alameda | | | | • |
| | CITY, TOWN Compton | | | | _VICINITY OF | | COUNTY Los Angeles | STATE California | 90220 |
| 3 PHOTO REFERENCE | | | | | | | | | |
| | PHOTO CREDIT | Harold Sanders | | | DATE OF PHOTO | August 1975 | | | |
| | NEGATIVE FILED AT | Del Amo Torrance | Phote, Ca | ograph liforn | y ia | | | | |
| .4 | IDENTIFIC | ATION | | | | | | | |
| | DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET | | | | TREET | | ΡΗΟΤΟ ΝΟ | 545 | |

Interior, "sala" (sitting room)