

Photo by Jim Bonar, October 1985; neg. with Texas Historical Commission, Austin. South elevation camera facing north Photo 1 of 11



Photo by Jim Bonar, October 1985; neg. with Texas Historical Commission, Austin.

Northeast oblique camera facing southwest Photo 2 of 11



Photo by Jim Bonar, October 1985; neg. with Texas Historical Commission, Austin.

Southwest oblique camera facing northeast Photo 3 of 11



Texas State Capitol Building, east elevation, October, 1985 Photograph by Jim Bonar, courtesy of Texas Historical Commission



Texas State Capitol Building, interior view of rotunda and dome, 1980 Photograph by Jim Bonar, courtesy of the Texas Historical Commission



Photo by Jim Bonar, October 1985; neg. with Texas Historical Commission, Austin.

South lobby, first floor camera facing northeast

Photo 7 of 11



Photo by Jim Bonar, October 1985; neg. with Texas Historical Commission, Austin.

House of Representatives chamber second floor

camera facing west

Photo 8 of 11



Texas State Capitol Building, Senate chamber, facing east, October, 1985 Photograph by Jim Bonar, courtesy of Texas Historical Commission



Photo by Jim Bonar, October 1985; neg. with Texas Historical Commission, Austin.

Main east-west corridor camera facing east

Photo 10 of 11



Photo by Jim Bonar, October 1985; neg. with Texas Historical Commission, Austin.

Detail of rotunda camera facing west

Photo 11 of 11