



ASA CHANDLER HOUSE

Elberton Vicinity, Elbert County, Georgia

Photographer: James R. Lockhart

Negatives Filed: Georgia Department of  
Natural Resources

Date: March, 1981

Description (1 of 13): Front facade of  
house; photographer facing northeast





ASA CHANDLER HOUSE

Elberton Vicinity, Elbert County, Georgia

Photographer: James R. Lockhart

Negatives Filed: Georgia Department of  
Natural Resources

Date: March, 1981

Description (2 of 13): Northwest side of  
house; photographer facing east.





ASA CHANDLER HOUSE

Elberton Vicinity, Elbert County, Georgia

Photographer: James R. Lockhart

Negatives Filed: Georgia Department of  
Natural Resources

Date: March, 1981

Description (3 of 13): Southeast side of  
house and well house; photographer facing  
northwest.





ASA CHANDLER HOUSE

Elberton Vicinity, Elbert County, Georgia

Photographer: James R. Lockhart

Negatives Filed: Georgia Department of  
Natural Resources

Date: March, 1981

Description (4 of 13): Rear of house;  
photographer facing southwest.





ASA CHANDLER HOUSE

Elberton Vicinity, Elbert County, Georgia

Photographer: James R. Lockhart

Negatives Filed: Georgia Department of  
Natural Resources

Date: March 1981,

Description( 5 of 13): First floor front  
parlor; photographer facing southwest.





ASA CHANDLER HOUSE

Elberton Vicinity, Elbert County, Georgia

Photographer: James R. Lockhart

Negatives Filed: Georgia Department of  
Natural Resources

Date: March, 1981

Description (6 of 13): First floor parlor  
and hall; photographer facing south.





ASA CHANDLER HOUSE

Elberton Vicinity, Elbert County, Georgia

Photographer: James R. Lockhart

Negatives Filed: Georgia Department of  
Natural Resources

Date: March, 1981

Description ( 7 of 13): First floor rear  
living room; photographer facing northwest.





ASA CHANDLER HOUSE

Elberton Vicinity, Elbert County, Georgia

Photographer: James R. Lockhart

Negatives Filed; Georgia Department of  
Natural Resources

Date: March, 1981

Description (8 of 13): First floor, stairs;  
photographer facing northeast.





ASA CHANDLER HOUSE

Elberton Vicinity, Elbert County, Georgia

Photographer: James R. Lockhart

Negatives Filed: Georgia Department of  
Natural Resources

Date: March, 1981

Description (9 of 13): Second floor north-  
west bedroom; photographer facing north.



ASA CHANDLER HOUSE

Elberton Vicinity, Elberton County, Georgia

Photographer: James R. Lockhart

Negatives Filed: Georgia Department of  
Natural Resources

Date: March, 1981

Description (10 of 13): Second floor south-  
east bedroom; photographer facing east.





ASA CHANDLER HOUSE

Elberton Vicinity, Elbert County, Georgia

Photographer: James R. Lockhart

Negatives Filed: Georgia Department of  
Natural Resources

Date: March, 1981

Description (11 of 13): Outbuildings to  
north of house; photographer facing north.







ASA CHANDLER HOUSE

Elberton Vicinity, Elbert County, Georgia

Photographer: James R. Lockhart

Negatives Filed: Georgia Department of  
Natural Resources

Date: March, 1981

Description (12 of 13): Interior of out-  
building to north of house; photographer  
facing northeast.



TOWNEHOUSE HOME CENTER

ASA CHANDLER HOUSE

Elberton Vicinity, Elbert County, Georgia

Photographer: James R. Lockhart

Negatives Filed: Georgia Department of  
Natural Resources

Date: March, 1981

Description (13 of 13): Tenant house,  
recently destroyed; photographer facing  
northeast.