



CONCENTRATED

PHOTO 1

Northwest corner of Daniel  
Tilden house showing the  
original structure and the  
two subsequent additions.

Daniel Tilden house,  
Peninsula, Ohio

Photographed by Edward  
Adelman in Fall 1982

Negative retained by  
Technical & Professional  
Division of Cuyahoga Valley  
National Recreation Area

Photo #1 Northwest corner  
of house



PHOTO 2

West side view of Daniel  
Tilden house.

Daniel Tilden house  
Peninsula, Ohio

Photographed by Edward  
Adelman in Fall 1982

Negative retained by  
Technical & Professional  
Assistance Division of  
Cuyahoga Valley National  
Recreation Area

Photo #2 West gable end  
of original building



PHOTO 3      Enlarged view of decorative  
gable on western side of  
Daniel Tilden house.

Daniel Tilden house  
Peninsula, Ohio

Photographed by Edward  
Adelman in Fall 1982

Negative retained by  
Technical & Professional  
Assistance Division of  
Cuyahoga Valley National  
Recreation Area

Photo #3 Detailed view  
of west gable





PHOTO 4 Overall view of typical  
interior door and casing  
of Daniel Tilden house.

Daniel Tilden house  
Peninsula, Ohio

Photographed by Edward  
Adelman in Fall 1982

Negative retained by  
Technical & Professional  
Assistance Division of  
Cuyahoga Valley National  
Recreation Area

Photo #4 Door leading from  
dining room into kitchen






PHOTO 5 Detail view of locking  
mechanism of pocket door  
in parlor of Daniel Tilden  
house.

Daniel Tilden house  
Peninsula, Ohio

Photographed by Edward  
Adelman in Fall 1982

Negative retained by  
Technical & Professional  
Assistance Division of  
Cuyahoga Valley National  
Recreation Area

Photo #5 Detailed view of  
locking mechanism of  
pocket doors in living room



PHOTO 6 Detail view of plinth at  
base of typical interior  
door casing of Daniel Tilden  
house.

Daniel Tilden house.  
Peninsula, Ohio

Photographed by Edward  
Adelman in Fall 1982

Negative retained by  
Technical & Professional  
Assistance Division of  
Cuyahoga Valley National  
Recreation Area

Photo #6 Detailed view of  
hand carved plinth on  
dining room doorway leading  
to hallway





PHOTO 7 Detail view of plinth and  
door knob of typical interior  
door and casing of Daniel  
Tilden house.

Daniel Tilden house  
Peninsula, Ohio

Photographed by Edward  
Adelman in Fall 1982

Negative retained by  
Technical & Professional  
Assistance Division of  
Cuyahoga Valley National  
Recreation Area

Photo #7 Detailed view of  
typical door and casing