DESCRI	PTION	IDENTIFICATION 5
Asphali shingle Bailt up Tile Other	1/Greek Revival (transitional)	ON CTICUT 06106 UTM 18 6 9:4 7:4:0 4:6 3:3 9:8:0 OUAD: OUAD: INCOMP TEAL LOOMIS, Jr. House Sor Avenue OCK 44, lot 12; .72 acre dsor Ave., Windsor CT pablic Vincina Same 06095
TOMPILED BY PHOTO PAGE 15 THERE TO COMPILED BY PHOTO PAGE 17 THERE TO COMPILED BY PAGE 17 THERE TO COMPILED	SOURCES SIGNIFICANCE	DESCRIPTION (Continued)

2 story masonry dwelling 3 bays wide by 2 bays deep, with pitched roof, rear 1 story ell, and south side veranda. Roof has a box cornice with complete return across the gable-end. Paired end-chimneys, (originally 4, now only 2) rise above the roof ridge. Gable has single eliptical window. Fenestration is symmetrical with 6 x 6 sash in a simple frame with cut-stone block lintel and sill. The entry is off-centered and has a paneled door with sidelights and transom. Over the entry is a gabled entry porch, (added c. 1880). It has turned posts, elaborate gable screen with lattice and fan motif, and turned hammer beam. From this entry porch extends the veranda. It has turned posts with small brackets and a polygonal hip roof.

The rear ell has gabled entry porch as well as dormer (both late 19th century) additions).

rn garage; noncontributing 75 Broad Street, Windsor, CT 06095 This house was built by Ira Loomis Jr. in 1835 on land given to him by his ather. (Ira Loomis, Sr. lived just south of here at 1037 Windsor Avenue.) He was farmer and brick maker. Example of a handsome early 19th century dwelling, constructed in masonry. The suse is a transitional Federal/Greek Revival style building. The eliptical gable indow being of the Federal period and the block lintels and door treatment of the lanning Consultant, Town of Windsor ose at 860, 881, 901, 958, and 1021 Windsor Avenue. each Revival era. The porch is a late 19th century addition and is a beautiful cample of the carpenters craftsmenship of this period. Compare the house with HISTORICAL OR ARCHITECTURAL IMPORTANCE AUCHITECA eston Maynard iles: Vol. II, page 448 LAS AD BRICING ON SILE chael K. O'Leary 98 and 1869 Maps S. Census Tract Records: 1880 ndsor Land Records: Vol. 34, page 167 wn of Windsor Assessor's Office st (front) Private Highways Deterioration ☐ Vandalısın NEGATIVE ON FILE CHC, Sheet #21 Developers 31.00 Spring, 1981 4/10/81 Oshar This

HIST 6 NEW 5 77 HEACK