

Gloria Mills March 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 1. 7 John Andrew Miller House viewed from U. S. Highway 460 looking north.



Gloria Mills March 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 2. Miller House viewed from southeast.


MAY 31 1977



Gloria Mills March 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 3. Miller House viewed from southwest.

Poe MAY 3 1 1977



Gloria Mills March 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 4. Stone section's western wall. Note gabled enclosure leading to basement and garret windows flanking

chimney.


7° NOV 9 1977



Gloria Mills March 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 5 Mantel in stone section.

MAY 31 1977



Gloria Mills March 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 6.77Fireplace in stone section revealing original masonry.

MAY 31 1977



Gloria Mills March 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 7. Door in stone section. Note diagonally placed boards.

9.4NOV 9 1977 MAY 3 1 1977