



Rust Mansion

Tacoma, Washington

Caroline Gallacci (1/1985)

State Historic Preservation Office

South and east elevation, looking
northwest

1/18



Rust Mansion
Tacoma, Washington

Caroline Gallacci (1/1985)
State Historic Preservation Office

West and south elevation, looking
northeast

2/18



Rust Mansion

Tacoma, Washington

Caroline Gallacci (1/1985)

State Historic Preservation Office

South elevation, looking north

3/18



Rust Mansion

Tacoma, Washington

Caroline Gallacci (1/1985)

State Historic Preservation Office

North and east elevation, looking
southwest

4/18



Rust Mansion

Tacoma, Washington

Caroline Gallacci (1/1985)

State Historic Preservation Office

Stairway at landing, looking west

5/18



Rust Mansion


Tacoma, Washington

Caroline Gallacci (1/1985)

State Historic Preservation Office

Stairway at second floor hall,
looking southwest

6/18



Rust Mansion

Tacoma, Washington

Caroline Gallacci (1/1985)

State Historic Preservation Office

East wall and fireplace in family
sitting room, second floor

7/18



Rust Mansion

Tacoma, Washington

Caroline Gallacci (1/1985)

State Historic Preservation Office

North wall in guest sitting room,
second floor, looking northwest

8/18



Rust Mansion

Tacoma, Washington

Caroline Gallacci (1/1985)

State Historic Preservation Office

West wall and fireplace in basement
ballroom, looking northwest

9/18



Rust Mansion

Tacoma, Washington

Caroline Gallacci (1/1985)

State Historic Preservation Office

Entry and orchestra chamber in
basement ballroom, looking northeast
10/18



Rust Mansion

Tacoma, Washington

Caroline Gallacci (1/1985)

State Historic Preservation Office

First floor reception showing alcove
fireplace, looking southeast

11/18



Rust Mansion

Tacoma, Washington

Caroline Gallacci (1/1985)

State Historic Preservation Office

First floor living room and sitting
room alcove, looking west

12/18



Rust Mansion

Tacoma, Washington

Caroline Gallacci (1/1985)

State Historic Preservation Office

First floor dining room, looking
northeast

13/18



Rust Mansion


Tacoma, Washington

Caroline Gallacci (1/1985)

State Historic Preservation Office

First floor library, looking west

14/18



Rust Mansion
Tacoma, Washington

Caroline Gallacci (1/1985)
State Historic Preservation Office

First floor door detail, dining
room, looking south to reception
15/18



Rust Mansion

Tacoma, Washington

Caroline Gallacci (1/1985)

State Historic Preservation Office

First floor detail, reception room,
looking east toward ladies reception

16/18



Rust Mansion

Tacoma, Washington


Caroline Gallacci (1/1985)

State Historic Preservation Office

First floor living room ceiling

detail

17/18



Rust Mansion

Tacoma, Washington

Caroline Gallacci (1/1985)

State Historic Preservation Office

First floor ladies reception room
ceiling and door detail, looking
west -- 18/18