

L 17 1980

1980

Photograph #1//0



William McCredie House 2606 Old Stage Road

View: North east view.



The William McCredie House

2606 Old Stage Road

Medford, Jackson County, Oregon

Photographer: Kenn Knackstedt

Negative: U.S. Forest Service

Date of Photo: March, 1978

View: East elevation (and South, rear).



William McCredie House 2606 Old Stage Road Medford, Jackson County, Oregon Photographer: Kenn Knackstedt Negative: U.S. Forest Service Date of Photo: March, 1978 View: North-west elevations

111 7 2 1980



```
Photograph #5/10
```

William McCredie House 2606 Old Stage Road Medford, Jackson County, Oregon Photographer: Kenn Knackstedt Negative: U.S. Forest Service Date of Photo: March, 1978 View: North-elevation (eaves detail)

JUL 17 1980



## Photograph #6//O

William McCredie House
2606 Old Stage Road
Medford, Jackson County, Oregon
Photographer: Kenn Knackstedt
Negative: U.S. Forest Service
Date of Photo: March, 1978
View: Detail of Front Door

JUL 1 7 1980



William McCredie House
2606 South Stage Road
Medford, Jackson County, Oregon
Photographer: Kenn Knackstedt
Negative: U.S. Forest Service
Date of Photo: March, 1978
View: Interion: Newell Post and baluster

70F I 1 1880

EP 17 1980



William McCredie House 2606 South Stage Road Medford, Jackson County, Oregon Photographer: Kenn Knackstedt Negative: U.S. Forest Service Date of Photo: March, 1978

View: Interior: Doorways Downstairs

7 1 1 1 1980




## Photograph #9//o

William McCredie House 2606 Old Stage Road Medford, Jackson County, Oregon Photographer: Kenn Knackstedt Negative: U.S. Forest Service

Date of Photo: March, 1978 View: Interior: Detail of Window trima dn wainscot

11 7 1980 JUL 1 7 1980



Photograph #10//6

2606 Old Stage Road
Medford, Jackson County, Oregon
Photographer: Kenn Knackstedt
Negative: U.S. Forest Service
Date of Photo: March, 1978 (from 1976 photo)
View: aerial view of Site Plan for William
McCredie House prior to development of Forest Service
Nursery.

JUL 1 7 1980

SEP 17 1980

William McCredie House



Mark Adams Photo, 1986 2685 Old Stage Road Central Point OR 97502

1 of 10 Northeast elevation (principal) facade, showing native oaks which are common to original and present 2/0/1



2685 Old Stage Road Central Point OR 97502


Mark Adams Photo, 1986

2 of 10 Northeast elevation (principal facade). Brick stove chimney is to be reconstructed around exposed flue.



Mark Adams Photo, 1986 2685 Old Stage Road Central Point OR 97502

3 of 10 Southeast elevation.



Mark Adams Photo, 1986 2685 Old Stage Road Central Point OR 97502

4 of 10 Southwest and southeast elevations.

12/17




2685 Old Stage Road Central Point, Jackson County, Oregon

Mark Adams Photo, 1986 2685 Old Stage Road Central Point OR 97502

McCredie, William, House

5 of 10 Southwest (rear) elevation.



Mark Adams Photo, 1986 2685 Old Stage Road Central Point OR 97502

6 of 10 Northwest and southwest elevations.

64/6/



2685 Old Stage Road Central Point, Jackson County, Oregon

Mark Adams Photo, 1986 2685 Old Stage Road Central Point OR 97502

McCredie, William, House

```
7 of 10
Northwest elevation, showing concrete
block foundation, which is to be
finished with stucco to resemble
```

original concrete perimeter foundation.



Mark Adams Photo, 1986 2685 Old Stage Road Central Point OR 97502

8 of 10 Staircase viewed from front parlor.



Mark Adams Photo, 1986 2685 Old Stage Road Central Point OR 97502

9 of 10 Detail of newell post, staircase between front parlor and kitchen.



Mark Adams Photo, 1986 2685 Old Stage Road Central Point OR 97502

10 of 10 Parlor doorway, showing typical door trim and baseboard molding.