


U.S. Department of the Interior Building 18th and C. Sts., NW Washington, D.C. Photographer: unknown Date of photo: ca. 1936 Neg: from the Waddy Wood Papers, Architectural Records Collection, Office of the Curator, Smithsonian Bldg., Smithsonian Institution, Washington, D.C. East Elevation. View of the east facade from the intersection of 18th and C Sts., NW



U. S. Department of the Interior Building 18th and C Sts., NW Washington, D.C. Photographer: A. T. Kelley Date of photo: April 4, 1938 Neg: NPS Historic Negative Collection View of south elevation, main entrance, prior to construction of Simon Bolivar Park and the Pan American Union Complex



The U.S. Department of the Interior Building 18th and C Sts., NW Washington, D.C. Photographer: A. T. Kelley Date of photo: June 14, 1938 Neg: NPS Historic Negative Collection Aerial view from the Washington Monument, with Pan American Union, DAR Building, Constitution Hall, and the Red Cross Annex in the foreground.



U. S. Department of the Interior Building 18th and C Sts., NW Washington, D.C. Public Buildings Service Photo., 1939. Photo No. 121-PS-40-68 in the National Archives, Washington, D.C. "Rush for the Oklahoma Land--1889" by John Steuart Curry, 1939. East Wall, North of Elevator Lobby 1, Main Corridor, Fifth Floor. Oil on canvas.



U.S. Department of the Interior Building 18th and C Sts., NW Washington, D.C. Public Buildings Service Photo No. 121-PS-3848 in the National Archives, Washington, D.C. (date unknown) "Themes of the Bureau of Indian Affairs: Indian and Soldier" by Maynard Dixon, 1939. West Wall, South Lobby, Fourth Floor. Oil on canvas.




The U.S. Department of the Interior Building 18th and C. Sts., NW Washington, D.C. Photographer: G. W. Peart Date of photo: ca, 1940 Neg: NPS Historic Negative Collection North elevation. View of the north facade from the intersection of 19th St. and New York Ave., NW



U.S. Department of the Interior Building 18th and C. Sts., NW Washington, D.C Photographer: Brooks Photographers, Bethesda, MD Date of photo: 1976 Neg: HABS collection West elevation. View of the west facade from the intersection of 19th, C St., and Virginia Ave., NW



U. S. Department of the Interior Building 18th and C Sts. NW Washington, D. C. Photographer: Brooks Photographers, Bethesda, Maryland Date of photo: 1976 Neg: HABS Collection South elevation, with Simon Bolivar Park in the foreground. Although the building was constructed in 1935-36, the park was not created until 1957.



U. S. Department of the Interior Building 18th and C Sts., NW Washington, D.C. Photographer: Brooks Photographers, Bethesda, MD Date of photo: 1976 Neg: HABS collection "American Moose" by Boris Gilbertson, 1939, West Wall, North of Elevator Lobby, Main Corridor. Missouri marble, bas-relief sculpture.



U. S. Department of the Interior Building 18th and C. Sts., NW Washington, D.C. Photographer: Brooks Photographers, Bethesda, MD Date of photo: 1976 Neg: HABS Collection "Buffalo Doorknob." The buffalo doorknobs were designed for the Secretary of the Secretary's Suite (6000), the Under Secretary's Suite, the First Assistant Secretary's Suite, the Ass't. Secretary's Suite, the Secretary's Conference Rm., the former Art Gallery and the Library.



The U.S. Department of the Interior Building 18th and C. Sts., NW Washington, D.C. Photographer: Brooks Photographers, Bethesda, Maryland Date of photo: 1976 Neg: HABS Collection Upper Grand Stairs, Main Corridor, Second Floor. View looking south toward the William Gropper Mural ("Construction of a Dam") and down the Grand Stairs toward the first floor.