

Photo 1. Main facade, fence and yard, looking west.

JUN 6 1978



NOV 14 1978

Photo 2. Main facade, looking west.

JUN 6 1978



Photo 3. Main and west facade, streetscape, looking southwest.

NOV 14 1978 JUN 6 1978



NOV 14 1978

Photo 4. Detail of stylized cast-iron fence & limestone curb, looking west.

JUN 6 1978



NOV 1 4 1978 Photo 5. Interior view of stairway and hall, looking west.

JUN 6 1978



JUN 6 1978

Photo 6. Interior view of middle parlor with pier mirror in bay, looking south.



Photo 7. Interior view of dining room with highly carved walnut mantel,

looking southwest.

NOV 1 4 1978 JUN 6 1978



Photo 8. Interior view of entrance hall and doorway, looking east.

JUN 6 1978



Photo 9. View of highly detailed I hinges with Chinoiserie motifs on all doors on first floor, looking west. JUN 6 1978



Photo 10. View of stained and leaded windows in stairwell, looking northeast.

JUN 6 1978

NOV 1 4 1978