



Photograph #1

Marvin Tavern - Wilton, Connecticut

South & East Elevations, Southeast View

J. Gardner, May 1983

Negative on file at Connecticut Historical Commission



Photograph #2

Marvin Tavern - Wilton, Connecticut

East Elevation, East View

J. Gardner, May 1983

Negative on file at Connecticut Historical Commission



Photograph #3

Marvin Tavern - Wilton, Connecticut

South Elevation, South View

J. Gardner, May 1983

Negative on file at Connecticut Historical Commission



Photograph #4

Marvin Tavern - Wilton, Connecticut

North Elevation, Northeast View

J. Gardner, May 1983

Negative on file at Connecticut Historical Commission





Photograph #5

Marvin Tavern - Wilton, Connecticut

West Elevation, N/W View

J. Gardner, May 1983

Negative on file at Connecticut Historical Commission



Photograph #6

Marvin Tavern - Wilton, Connecticut

East Elevation, Main Entrance

J. Gardner, May 1983

Negative on file at Connecticut Historical Commission



Photograph #7

Marvin Tavern - Wilton, Connecticut

South & West Elevations, Southwest View

J. Gardner, May 1983

Negative on file at Connecticut Historical Commission



Photograph #8

Marvin Tavern - Wilton, Connecticut

Main Staircase, facing west

J. Gardner, May 1983

Negative on file at Connecticut Historical Commission





Photograph #9

Marvin Tavern - Wilton, Connecticut

Main Parlor Baseboard, facing south

J. Gardner, May 1983

Negative on file at Connecticut Historical Commission



Photograph #10

Marvin Tavern - Wilton, Connecticut

West Parlor Fireplace, facing east

J. Gardner, May 1983

Negative on file at Connecticut Historical Commission



Photograph #11

Marvin Tavern - Wilton, Connecticut

West Parlor Sill Panel, facing south

J. Gardner, May 1983

Negative on file at Connecticut Historical Commission



Photograph #12

Marvin Tavern - Wilton, Connecticut

North Parlor, facing southwest

J. Gardner, May 1983

Negative on file at Connecticut Historical Commission






Photograph #13

Marvin Tavern - Wilton, Connecticut

Master Bedroom Window, facing southeast

J. Gardner, May 1983

Negative on file at Connecticut Historical Commission



Photograph #14

Marvin Tavern - Wilton, Connecticut

Master Bedroom, facing west

J. Gardner, May 1983

Negative on file at Connecticut Historical Commission



Photograph #15

Marvin Tavern - Wilton, Connecticut

West Wing Parlor, facing west

J. Gardner, May 1983

Negative on file at Connecticut Historical Commission



Photograph #16

Marvin Tavern - Wilton, Connecticut

Basement Oven, facing south

J. Gardner, May 1983

Negative on file at Connecticut Historical Commission