

Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust

view from northeast

1/24



Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust view from southeast

2/24



# Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust bulkhead entrance from southeast

3/24



Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust detail. dated lintel over bulkhead entrance

4/24



Rockland Farm CARR-342 10 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust view from southwest



#### 10 Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust west elevation



Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust view from northwest



Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust Kiche, camera facing southwest




Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust Kiche, fireplace detail



## Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust east entrance doors from interior



Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust stair, northeast corner of Kiche 11/24



Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust detail, crossetted architrave in Stube



Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust southeast room, 2nd floor



Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust southwest room, 2nd floor



Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust stair to attic, 2nd floor, northeast corner



#### Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust head/of stair, northeast corner of attic



Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust exposed roof framing in attic



Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust detail of strap hinge and surround, west entrance door



Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust detail, Dutch elbow lock, souteast room 2nd floor

19/24




## Rockland Farm

CARR-342

Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust

detail, batets and abatistic states in NE corner of kiche 20/24



## Rockland Farm



Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust

detail, thumblated, door to strin in All corner of Kateries latch and chairrail, Stube

21/24



Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust springhouse foundation, view from west 22/24





Something went wrong while we were encoding this page. Please check the log file to find out the details.



Rockland Farm CARR-342 Carroll County, Maryland Photo by Joe Getty, August 1985 Negative at Maryland Historical Trust corn crib. view from southwest 24/24