

Photo 1

General view looking northwest of the facade at present

Photographer: Craig Leonard

Date: October 1987

Negatives: 521 West Market Street Bluffton, Indiana 47614



Photo 2

Historic view, looking northwest, c. 1890. Photo by Felix Schanz, Collection Herb Harnish



Photo 3


Historic view looking northwest in 1918, Schmitz Block at center. Collection Allen County Historical Society



Photo 3A

Historic view looking northwest c. 1928, showing the first floor facades with show windows added after the original construction. Collection Robert Goldstein.

Photographer: Craig Leonard Date: (copy) February 1988 Negatives: 521 West Market Street Bluffton, IN 46714



ARIS STORE EXPANDS—Under the extensive remodeling and expansion program of Hutner's Paris Store, announced by President Ben Hutner today, the store will take over the entire second and third Boors of the Noll Building, above, extending the store from its present location at 920 and 922 South Calhoun St. and Washington Blvd.

## Capt. Odom

(Continued from Page 1) .

Ry Vida Hurst

## INFATUATION

low by my sliding the pilot's seet

Photo 4

Historic view looking northwest from the Fort Wayne News-Sentinel August 11, 1947, p.  $\overline{11}$ .



Photo 5

Detail view looking southwest of original first floor pier behind modern cladding on south elevation



Birds-eye View Fort Wayne, Ind.

Photo 6

Postcard view looking southeast in 1910, showing rear elevations



Photo 7

General view looking southeast of rear elevations at present



Photo 8

General view looking southeast in south first floor store room



Photo 9

General view looking west in the middle first floor store room



Photo 10

Detail view looking west of the ceiling in the middle first floor store room



Photo 11

General view looking west in the north first floor store room



Photo 12

Detail view of joists and remains of metal ceiling above modern ceiling, north first floor store room



Photo 13

General view looking north in the second floor hallway



Photo 14

General view looking west in the third floor hallway



Photo 15

General view looking north in the fourth floor hallway

Photographer: Craig Leonard Date: October 1987

Negatives: 521 West Market Street Bluffton, Indiana 46714



Photo 16

Detail view looking northwest of the second floor stair landing



Photo 17

Detail view looking southeast on the fourth floor, showing typical office casing and baseboard trim



Photo 18

Detail view looking north on the third floor, showing typical door