



Duncan House
Franklin, Kentucky

PHOTO 1
Front elevation facing east.



3011

Duncan House
Franklin, Kentucky

PHOTO 2

Detail of front porch and
front door.



Duncan House
Franklin, Kentucky

PHOTO 3

Detail of two story front porch



Duncan House
Franklin, Kentucky

PHOTO 4

Corner elevation facing southwest.



Duncan House
Franklin, Kentucky

PHOTO  5

Rear elevation facing west.



Duncan House
Franklin, Kentucky

PHOTO 6

Corner elevation showing side
porch and facing southwest.



Duncan House
Franklin, Kentucky

PHOTO

7

Corner elevation facing northwest.



Duncan House
Franklin, Kentucky

PHOTO **8**

Cast iron mantel in upstairs of
Section B.



Duncan House
Franklin, Kentucky

PHOTO 9

Wood mantel in Section D.



Duncan House
Franklin, Kentucky

PHOTO 10

Door Detail in Section B.