



McCracken-Wilgus House

Lexington, 327 Wilgus St., Fayette Co., Ky.

Walter Langsam

253 Market St.

Lexington, Ky.

June, 1978

DEC 22 1978

Photo 1. Front porch from southeast.



McCracken-Wilgus House

Lexington, 327 Wilgus St., Fayette Co., Ky.

Walter Langsam

DEC 22 1978

253 Market

Lexington, Ky.

June, 1978

Photo 2. Rear wall with original ell removed. Shows rear room of west wing. From northeast.



John McCracken House
McCracken-Wilgus House

Lexington, 327 Wilgus St., Fayette County, Kentucky

Walter Langsam


253 Market St.

Lexington, Ky.

June, 1978

DEC 22 1978

Photo 3. John McCracken House, west wing and facade of original house from southwest.




McCracken-Wilgus House
Lexington, 327 Wilgus St., Fayette Co., Ky.

Walter Langsam
253 Market
Lexington, Ky.
June, 1978

DEC 22 1978

Photo 4. Front door from south.



~~McCracken-Wilgus House~~
McCracken-Wilgus House

Lexington, 327 Wilgus St., Fayette Co., Ky.

Walter Langsam

DEC 22 1978

253 Market St.

Lexington, Ky.

June, 1978

Photo 5. Door from original room into ell (now gone). From north.



McCracken-Wilgus House

Lexington, 327 Wilgus St., Fayette Co., Ky.

Walter Langsam

253 Market St.

Lexington, Ky.

June, 1978

DEC 22 1978

Photo 6. Mantel in original downstairs room. From east.



John McCracken
McCracken-Wilgus House

Lexington, 327 Wilgus St., Fayette Co., Ky.

Walter Langsam

253 Market St.

Lexington, Ky.

June, 1978

DEC 22 1978

Photo 7. Mantel in original upstairs room. From east.



McCracken-Wilgus House

Lexington, 327 Wilgus St., Fayette Co., Ky.

DEC 22 1978


Walter Langsam

253 Market

Lexington, Ky.

June, 1978

Photo 8. Chandelier medallion in parlor ceiling of east wing.



McCracken-Wilgus House

Lexington, 327 Wilgus St., Fayette Co., Ky.

DEC 22 1978

Walter Langsam

253 Market St.

Lexington, Ky.

June, 1978

Photo 9. Window in east wing parlor on east wall. From southwest.