1-22

SURVEY-INVENTORY FORM

Photograph Negative No.:

4-10

MAY 1 6 1985

### COMMUNITY CULTURAL RESOURCE SURVEY

NAME 1. Historic

PEARSON HOUSE

and/or Common

2. LOCATION UTM References:

515580 Zone 10 Easting

Street & Number

27th Street 1939

Northing 5329360

- not for publication

City, Town

Port Townsend

- vicinity of

State

Washington

County Jefferson

3. CLASSIFICATION

Present Use:

Ownership:

public

both private

Status:

occupied

unoccupied work in progress

agriculture commercial educational

entertainment government

industrial private residence military museum park

religious scientific other: transportation

OWNER OF PROPERTY 4.

Name

Harold S. and Martha Rohring

Street & Number

1939 27th Street

City, Town Port Townsend

vicinity of

State Washington 98368

5. MAJOR BIBLIOGRAPHICAL REFERENCES

Dorothy Wallace, former owner, telephone interview 11/5/1984

FORM PREPARED BY

Name/Title

Katheryn Krafft and Shirley Courtois

Organization Date November 1984 Street & Number Telephone (206) 325-9346 4021 E. Highland Drive

City or Town Seattle

State Washington 98112

## 7. DESCRIPTION

Condition:

excellent

good

fair deteriorated

ruins unexposed

Circle one:

unaltered

altered

Circle one:

original site

moved date

Describe the present and original (if known) physical appearance attach photo

This is a simple rectangular, two-story, wood frame structure with a post and pier foundation. The gable roof is covered with asphalt shingles. The majority of the original siding is presently covered by asbestos shingle siding, although fancy butt wood shingles are in place at the gable ends. Windows are tall, narrow, one-over-one light, double-hung sash with elaborate surrounds that include heavy bracketed entablature heads. At the wide eaves beneath a boxed cornice, ornate curved brackets with drop finials alternate with recessed panels of the frieze and circular soffit ornaments. Additional turned and jig-sawn ornament adorns the front porch, which has turned posts and balusters and bracketed eaves. The gable end features an elaborate bargeboard with sawn and layered ornament and projecting turned spindles. A one-story bracketed wing, covered by a hip roof, extends from the rear elevation.

Verbal boundary description: Jas. Hussey's Addition,

Block 4, Lots 9-10

Acreage: Less than an acre

# 8. SIGNIFICANCE

Specific dates c. 1889

Builder/Architect

Unknown

#### a. History

According to a long-time former owner, the house was built about 1889 by the Pearson brothers for their mother. Reportedly, all of the ornament was custom made at the site, and in later years the lathes and other wood working tools were still housed in a shed on the premises. The asbestos shingle siding was applied prior to 1951.

# b. Evaluation of Significance

The Pearson House is the most richly ornamented of the modest vernacular residences which were so common in Port Townsend during the late Victorian period. The variety of decorative elements on such a small building is quite exceptional, and it gives the Pearson House a distinctive place in Port Townsend's building history.

