

Front Facades of 1735 and 1729-31 N.W. Irving, early 1970's. Oregon Historical Society, Negative R-454.

FEB 2 5 1980

Couch Family Investment Development 1721-1735 N.W. Irving 718 N.W. 18th Street Portland, Multnomah Co., Oregon

Oregon Historical Society Photo 1230 S.W. Park Avenue Portland, Oregon 97205

1 of 10 Front elevations of 1735 and 1729-31 N.W. Irving, Early 1970's. JAN 1 4 1980



Catherine Galbraith Photo, 1979 1415 S.W. Sherrett Street Portland, Oregon 97212

FEB 2 5 1980 2 of 10 View of 1735, 1729-31, 1721 N.W. Irving, Facing Northeast

JAN 14 1980 Front Facades of 1735, 1729-31, 1721 NW Irving, facing northeast. (Front Facades of Campbell Townhouses to East) Portland,Oregon. August,1979.



Catherine Galbraith Photo, 1979 1415 S.W. Sherrett Street Portland, Oregon 97212 FEB 2 5 1980

3 of 10 Side elevation, 1735 N.W. Irving, Facing Northeast

JAN 1 4 1980

Front and Side Facades of 1735, 1729-31, 1721 NW Irving facing northeast. Portland, Oregon. August, 1979



Catherine Galbraith Photo, 1979 1415 S.W. Sherrett Street Portland, Oregon 97212

4 of 10 Front (North) Elevation, 1735 N.W. Irving

> Front Facade of 1735 NW Irving, facing North. Portland, Oregon. August, 1979



Catherine Galbraith Photo, 1979 1415 S.W. Sherrett Street Portland, Oregon 97212

FEB 2 5 1980

5 of 10 Front (North)Elevation 1729-31 N.W. Irving JAN 14 1980

> Front Facade of 1729-31 NW Irving, facing North. Portland, Oregon. August, 1979



Couch Family Investment Development 1721-1735 N.W. Irving 718 N.W. 18th Street Portland, Multnomah Co., Oregon Catherin Galbraith Photo, 1979


1415 S.W. Sherrett Street Portland, Oregon 97212

6 of 10 Porch Detail 1721 N.W. Irving

FEB 2 5 1980

JAN 1 4 1980

Close-up of Front Facade/ Porch of 1721 NW Irving, facing Northwest. Portland, Oregon. August, 1979



Catherine Galbraith Photo, 1979 1415 S.W. Sherrett Street Portland, Oregon 97212

7 of 10 Detail of Bay Window 1729-31 N.W. Irving FEB 2 5 1980

JAN 1 4 1980

Partial view of projecting Bay Window at 1729-31 NW Irving, facing northeast. Portland, Oregon. August, 1979.



Catherine Galbraith Photo, 1979 1415 S.W. Sherrett Street Portland, Oregon 97212 FEB 2 5 1930

8 of 10 Interior of Attic 1735 N.W. Irving

JAN 1 4 1980

Interior of Attic at 1735 NW Irving, ceiling and room division. Portland, Oregon. August, 1979.



Catherine Galbraith Photo, 1979 1415 S.W. Sherrett Street Portland, Oregon 97212

9 of 10 Staircase Detail 1735 N.W. Irving

JAN 1 4 1980

Interior of Entry Hall of 1735 NW Irving, stairway detail and newel post. Portland, Oregon. August, 1979.



Catherine Galbraith Photo, 1979 1415 S.W. Sherrett Street Portland, Oregon 97212 FEB 2 5 1980

10 of 10 Detail of door and wainscotting (original) 1735 N.W. Irving JAN 1 4 1980

> Interior of Dining Room of 1735 NW Irving, original door and wainscotting. Portland, Oregon. August, 1979.