



Pickering Farm  
Issaquah, Washington

Steve Aubin  
October, 1979

Office of Archaeology & Historic Preservation

View of hay-barn and cow barn from the west.  
1 of 11



Pickering Farm  
Issaquah, Washington

Steve Aubin  
October, 1979

Office of Archaeology & Historic Preservation

North end and west side of 1890 hay barn,  
and west side of cow barn.

2 of 11



Pickering Farm  
Issaquah, Washington

Steve Aubin

October, 1979

Office of Archaeology & Historic Preservation

North end, east side of 1890 hay barn.

3 of 11



Pickering Farm  
Issaquah, Washington

Russell Woodruff

December, 1979

Office of Archaeology & Historic Preservation

May barn framing detail (crossbeam and brace,  
mortise-and-tenon joint)

4 of 11





Pickering Farm  
Issaquah, Washington

Joanne Murray

December, 1979

Office of Archaeology & Historic Preservation

Photographer: Joanne Murray, December, 1979

Hay barn framing detail (post and beam,  
mortise-and-tenon joint with mortise pins)

5 of 11



Pickering Farm  
Issaquah, Washington

Russell Woodruff  
December, 1979

Office of Archaeology & Historic Preservation  
Photographer: Russell Woodruff, December, 1979

Hay barn framing detail (post, cross-beam,  
tension rod, diagonal braces and eaves plate)  
6 of 11



The Pickering Farm

King County

Washington

View of the cow & hay barn from the SE

Pickering Farm  
Issaquah, Washington


Jake Thomas

July, 1900

Office of Archaeology & Historic Preservation

View of the cow and hay barn from the  
southeast

7 of 11



Pickering Farm  
Issaquah, Washington

Joanne Murray  
December, 1979

Office of Archaeology & Historic Preservation

Interior of 1906 cow barn, looking south  
3 of 11





The Pickering Farm  
King County  
Washington  
View of the bungalow residence from the  
West

Pickering Farm  
Issaquah, Washington

Jake Thomas  
July, 1930  
Office of Archaeology & Historic Preservation

View of the bungalow residence from the west  
9 of 11



The Pickering Farm

King County

Washington

View of the Second Hay Barn from the SW

Pickering Farm  
Issaquah, Washington

Jake Thomas

July, 1980

Office of Archaeology & Historic Preservation

View of the second hay barn (1936) from the  
southwest

10 of 11





The Pickering Farm  
King County  
Washington  
View of the storage shed from the NW

Pickering Farm  
Issaquah, Washington

Jake Thomas  
July, 1980  
Office of Archaeology & Historic Preservation

View of garage/storage shed from the  
northwest  
11 of 11