



Minterburn Mill, Vernon (Rockville) CT

Photograph 1, Adams Pond, Dam and Penstock

S. A. Abbott, 10/82

Neg. on faile: Conn. Historical Comm.,  
Hartford, CT





Abandoned Tailrace, Minterburn Mill, Rockville CT  
Photograph 2, S. A. Abbott, 10/82  
Neg. on file: Conn. Hist. Comm, Hartford, CT


Minterburn Mill, Vernon (Rockville) CT.

Photograph 2: Abandoned Tailrace

S. A. Abbott, 10/82

Neg. on file: Conn. Historical Comm.  
Hartford, CT





Minterburn Mill, Vernon (Rockville), CT

Photograph 3, South facade, bldg. no. 1

S. A. Abbott, 10.82

Newg. on file: Conn. Historical Comm.  
Hartford, CT



Minterburn Mill, Vernon (Rockville) CT

Photograph 4: View looking west, Roof,  
Bldg. No. 1

S. A. Abbott, 4/83

Neg. on file: Conn. Historical Comm.  
Hartford, CT





Minterburn Mill, Vernon (Rockville) CT

Photograph 5: Belfry, Bldg. No. 1

S. A. Abbott, 10/82

Neg. on file: Conn. Historical Comm.,  
Hartford, CT





Minterburn Mill, Vernon (Rockville), CT

Photograph 6: West elevation, Bldgs. 1, 3

S. A. Abbott, 10/82

Neg. on file: Conn. Historical Comm.,  
Hartford, CT





Minterburn Mill, Vernon (Rockville), CT

Photograph 7: Roof framing, Bldg. No. 1

S. A. Abbott, 4/83

Neg. on file: Conn. Historical Comm.  
Hartford, CT



Minterburn Mill, Vernon (Rockville) CT

Photograph 8: Detail, Kneebrace, Bldg. No. 1

S. A. Abbott, 4/83

Neg. on file: Conn. Historical Comm.  
Hartford, CT





Minterburn Mill, Vernon (Rockville), CT

Photograph 9, South facade, Bldg. No. 2

S. A. Abbott, 10/82

Neg. on file: Conn. Historical Comm.  
Hartford, CT



Minterburn Mill, Vernon (Rockville), CT

Photograph 10, North Elevation, Bldgs. 2 and 4

S. A. Abbott, 10/82

Neg. on file: Conn. Historical Comm.  
Hartford, CT






Minterburn Mill, Vernon (Rockville), CT

Photograph 11: Interior of Ground Floor

S. A. Abbott, 4/83

Neg. on file: Conn. Historical Comm.  
Hartford, CT



Minterburn Mill, Vernon (Rockville), CT

Photograph 12: Interior at Second Floor,  
Bldg. No. 2

S. A. Abbott, 4/83

Neg. on file: Conn. Historical Comm.  
Hartford, CT






Minterburn Mill, Vernon (Rockville), CT

Photograph 13: Interior at Fourth Floor,  
Bldg. No. 2

S. A. Abbott, 4/83

Neg. on file; Conn. Historical Comm.  
Hartford, CT



Minterburn Mill, Vernon (Rockville), CT

Photograph 14: Original freight elevator,  
Bldg. No. 2

S. A. Abbott, 4/83

Neg. on file: Conn. Historical Comm.  
Hartford, CT





Minterburn Mill, Vernon (Rockville), CT

Photograph 15: Northeast Corner, Bldg. No. 3

S. A. Abbott, 4/83

Neg. on file: Conn. Historical Comm.  
Hartford, CT



Minterburn Mill, Vernon (Rockville), CT

Photograph 16: Interior, Bldg. No. 3

S. A. Abbott, 4/83

Neg. on file: Conn. Historical Comm.  
Hartford, CT





Minterburn Mill,  
Vernon (Rockville), CT

Photograph 17  
West elevation, Chimney,  
Bldg. No. 4

S. A. Abbott, 4/83  
Neg. on file: Conn.  
Historical Comm. Hartford,  
CT