

Location: vicinity Georgetown, Delaware Photographer: Richard Carter Date: 9/1978 Location of Negative: Div. of Hist. & Cultural Affairs, B/A&HP, Old State House, The Green, Dover, Del. 19901 Description: View of front of house with brick section at left.

NOV 2 6 1980

Photograph Number:1 of




Location: Vicinity Georgetown, Delaware

- Photographers Richard Carter
- Date: 9/78
- Location of Negative: Div. of Hist. & Cultural Affairs, B/A&HP, Old State House, The Green, Dover, Del. 19901 Description: View of house showing frame section and shingled gable end of main house.

NOV 2 6 1980

Photograph Number: 2 of •




Location: Vicinity Georgetown, Delaware

Photographer: Richard Carter Date: 9/78 Location of Negative: Div. of Hist. & Cultural Affairs, B/A&HP, Old State House, The Green, Dover, Del. 19901 Description: View of house from the southwest

Photograph Number:

3 of •





Location: Vicinity Georgetown, Delaware

Photographers Richard Carter Date: 9/78

Location of Negative: Div. of Hist. & Cultural Affairs, B/A&HP, Old State House, The Green, Dover, Del. 19901 Description: Brick front showing alterations in brick work.

Photograph Numbers 4 of •





Location: Vicinity Georgetown, Delaware

Photogra \_\_Richard Carter Date: 9/78 Location c \_\_\_\_\_e: Div. of Hist. & Cultural Affairs, B/A&HP, Old State House, The Green, Dover, Del. 19901 Description. View showing west gable end with water table, belt course, and glazed header courses.

Photograph Number: 5 of •

NOV 2 6 1980



Location: Vicinity Georgetown, Delaware Photographer: Richard Carter Date: 9/78 Location of Negative: Div. of Hist. & Cultural Affairs, B/A&HP, Old State House, The Green, Dover, Del. 19901 Description: View of front brickwork showing raised front wall and old flemish bond brick work.

Photograph Number: 6 of 0





Location: Vicinity of Georgetown, Delaware


Photographer: Richard Carter

Date: 9/78

Location of Negative: Div. of Histl & Cultural Affairs, B/A&HP, Old State House, The Green, Dover, Delaware 19901 Description: View of southwest corner showing stuccoed water table.

Photograph Number: 7 of •

NOV 2 6 1980



Location: Vicinity Georgetown, Delaware

Photographer: Richard Carter Date: 9/78

Location of Negative: Div. of Hist. & Cultural Affairs, B/A&HP, Old State House, The Green, Dover, Del. 19901 Description: Detail of brickwork on southwest wall.

Photograph Number: **M** of **Q** 





8 Location: Vicinity Georgetown, Delaware 0 Photographer: Richard Carter 2 Date: 10/80 Location of Handlive: Sussex County Preservation Office, Sussex County Courthouse, Georgetown, Delaware 19947 Description: View of interior wall in stairwell; structure was originally only one bay wide in the 18th century.

Photograph Number: 9 of 11



Location: Vicinity Georgetown, Delaware

Photographer: Richard Carter Date: 10/80

Location of Negative: Sussex County Preservation Office, Sussex County Courthouse, Georgetown, Delaware 19947 Description: interior of gable end of brick section of the house; original ceiling boards of first floor used to sheath gable end after new roof was added in the 19th century

NOV 2 6 1980

Photograph Number: 10 of 11



Location: Vicinity Georgetown, Delaware Photographer: Richard Carter Date: 10/80 Location of Negative: Sussex County Preservation Office, Sussex County Courthouse, Georgetown, Delaware 19947 Description: starting place of water table of the original west end wall of the one-bay house; 19th century door tim at left and baseboard at night

Photograph Number: 11 of 11

