

Beebe Park 253 Market Street May, 1977

Photo No. 1 - Facade as seen looking northeast,



Beebe Park 253 Market Street May, 1977

Photo No. 2 - Ca. 1895 photo of facade of building looking northeast,



Beebe Park 253 Market Street May, 1977

Photo No. 3 - Side of building as seen from the southeast.



Beebe Park 253 Market Street May, 1977

Photo No. 4 - Side of building as seen from the northwest.



Beebe Park 253 Market Street May, 1977

Photo No. 5 - Detail of main doorway,



Benjamin McCann H^Ouse Lexington Fayette Kentucky

Beebe Park 253 Market Street May, 1977

Photo No. 6 - Staircase with detailing of baseboard,



Beebe Park 253 Market Street May, 1977

Photo No. 7 - First floor door frame showing Greek ears.



Beebe Park 253 Market Street May, 1977

Photo No. 8 - Stairway out of dining room leading to chamber above,



Beebe Park 253 Market Street May, 1977

Photo No. 9 - Ceiling centerpiece in hall.



Beebe Park 253 Market Street May, 1977

Photo No. 10 - Ceiling centerpiece in parlor,



Beebe Park 253 Market Street May, 1977

Photo No. 11 - Greek Revival mantel on second floor fireplace.



Beebe Park 253 Market Street May, 1977

Photo No. 12 - Greek Revival door on first floor.