

Photographer: Warren Jagger

Date: January 1982 Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, RI

Exterior view facing northeast

Photo #1.



Photographer: Warren Jagger
Date: January 1982
Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, RI

Exterior view facing southwest.

Photo #2.



Photographer: Warren Jagger

Date: January 1982

Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, RI

View of fireplace wall in present living room.

Photo #3.



Photographer: Warren Jagger Date: January 1982 Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street

Providence, RI

View of fireplace in the kitchen.

Photo #4.