



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc. Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). West & South Elevations, NE View
- 7). # 1



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc., Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). South & East Elevations, NW View
- 7). # 2



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc., Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). Main Entrance, Front (West) Elevation
- 7). #3



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc., Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). Front (West) Elevation, East View
- 7). #4



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc., Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). East & North Elevations, S.W. View
- 7). #5



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc., Sharpsburg, Maryland.
- 4). January, 1982
- 5). Preservation Associates, Inc.
- 6). First Floor Store Fronts, South Elevation
- 7). #6



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc., Sharpsburg, Maryland
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). North Elevation of East Addition, S. View
- 7). #7



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc., Sharpsburg, Maryland
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). First Floor, Main Corridor, E. View
- 7). #8



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc., Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). Main Staircase, First to Second Floors,
NE View
- 7). #9



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc., Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). Main Lobby, First Floor Staircase
- 7). #10



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates, Inc., Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). Main Lobby, N. View, Original Double Doors
- 7). #11



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc. Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). Staircase, First Floor, N. Office Suite
- 7). #12



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc., Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). Lighting, First Floor, N. Office Suite
- 7). #13



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc. Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). New Double Doors, First Floor, N. Office
Suite, N. View.
- 7). #14



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc., Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). New Oak Paneled Elevator, Behind Main
Staircase, Lobby.
- 7). #15



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc., Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). Second Floor, West Wall, S.W. View
- 7). #16



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc., Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). Second Floor Stair Landing
- 7). #17



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc., Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). Second Floor Corridor
- 7). #18



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc., Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). Second Floor Corridor
- 7). #19



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Douglass C. Reed, Preservation Associates,
Inc., Sharpsburg, Maryland.
- 4). January 1982
- 5). Preservation Associates, Inc.
- 6). First Floor, N. Office Suite, S. View
- 7). #20



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Photographer Unknown
- 4). 1884
- 5). Commercial Renovation & Development, Inc.
300 N. Main St., Wichita, Kansas
- 6). West & South Elevations, N.E. View
- 7). #21



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Photographer Unknown
- 4). 1904
- 5). Commercial Renovation & Development, Inc.
300 N. Main St., Wichita, Kansas
- 6). West Elevation, S.E. View
- 7). #22



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Jim Edwards, Merchandising Photography
Wichita, Kansas
- 4). 1979
- 5). Wichita, Kansas
- 6). West & South Facades, before restoration,
N.E. View
- 7). #23



BOG
Sandy
PARK
and

- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Jim Edwards, Merchandising Photography,
Wichita, Kansas
- 4). 1979
- 5). Wichita, Kansas
- 6). N. Elevation before restoration, S. View
- 7). #24



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Jim Edwards, Merchandising Photography,
Wichita, Kansas
- 4). 1979
- 5). Wichita, Kansas
- 6). E. and N. Elevations before restoration,
S.W. View
- 7). #25



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Jim Edwards, Merchandising Photography,
Wichita, Kansas.
- 4). 1979
- 5). Wichita, Kansas
- 6). S. & E. Elevations before restoration,
N.W. View
- 7). #26



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Jim Edwards, Merchandising Photography,
Wichita, Kansas
- 4). 1979
- 5). Wichita, Kansas
- 6). Second Floor Corridor, before restoration,
N. View.
- 7). #27



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Jim Edwards, Merchandising Photography
Wichita, Kansas
- 4). 1979
- 5). Wichita, Kansas
- 6). Second Floor Stair Landing, before res-
toration.
- 7). #28



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Jim Edwards, Merchandising Photography,
Wichita, Kansas
- 4). 1979
- 5). Wichita, Kansas
- 6). Main Stairway in Lobby, before restoration
- 7). #29



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Jim Edwards, Merchandising Photography,
Wichita, Kansas
- 4). 1979
- 5). Wichita, Kansas
- 6). Entrance to First Floor Offices, S. Side
of Building, before restoration
- 7). #30



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Jim Edwards, Merchandising Photography,
Wichita, Kansas
- 4). 1979
- 5). Wichita, Kansas
- 6). Entrance to First Floor Offices, N. side
of Building, before restoration.
- 7). #31



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Jim Edwards, Merchandising Photography,
Wichita, Kansas
- 4). 1979
- 5). Wichita, Kansas
- 6). Typical Second Floor Window, before res-
toration.
- 7). #32



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Jim Edwards, Merchandising Photography
Wichita, Kansas
- 4). 1979
- 5). Wichita, Kansas
- 6). Main Stairway between First and Second
Floors, before restoration.
- 7). # 33



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Jim Edwards, Merchanding Photography,
Wichita, Kansas
- 4). 1979
- 5). Wichita, Kansas
- 6). Doors to Old Billiard Room (now elevator
lobby), First Floor, before restoration.
- 7). #34



- 1). Occidental Hotel
- 2). Wichita, Kansas
- 3). Jim Edwards, Merchandising Photography,
Wichita, Kansas
- 4). 1979
- 5). Wichita, Kansas
- 6). "Bridal Chamber", Second Floor, Southeast
Corner, before restoration.
- 7). #35