


WILLOOX COMMERCIAL COMPANY 180 N. Railroad, Willcox, Arizona Photo by Dale Seidel November 1981 Negative on file at Willcox Commercial Co. Camera facing North-west Phote 1 of 6



WILLCOX COMMERCIAL COMPANY 180 N. Railroad, Willcox, Arizona Photo by Dale Seidel November, 1981 Negative at Willcox Commercial Company Camera facing South-west Photo 2 of 6




WILLCOX COMMERCIAL COMPANY 180 N. Railroad, Willcox, Az. Photo by Dale Seidel November 1981 Negative on file at Willcox Commercial Co. Camera facing Southeast Photo 3 of 6



Willcox Commercial Company 180 N. Railroad Ave., Willcox, AZ Photo by Dale Seidel, December 1982 Negative on file at Willcox Commercial Co. Camera facing southwest Photo 4 of 6



Willcox Commercial Company 180 N. Railroad Ave., Willcox, AZ Photo by Dale Seidel, December 1982 Negative on file at Willcox Commercial Co. Interior, looking west at office balcony Photo 5 of 6



Willcox Commercial Company 180 N. Railroad Ave., Willcox, AZ Photo by Dale Seidel. December 1932 Negative on file at Willcox Commercial Co. Detail of pressed metal ceiling Photo 6 of 6