



Street view, 1500-1600 block of Roma NE

Spruce Park Historic District

Albuquerque, New Mexico

View looking northwest, Tessier House (1517

Roma) second from left

Mary Davis December, 1980

Albuquerque Historic Landmarks Survey



Street view, 1200 block of Roma NE
Spruce Park Historic District
Albuquerque, New Mexico

View looking southeast; 1212, 1218 Roma
(both non-contributing) at left center
Mary Davis December, 1980
Albuquerque Historic Landmarks Survey



Kaseman House, 1420 Las Lomas N.E.

#7

Spruce Park Historic District


Albuquerque, New Mexico

Built 1926

View from northeast

Christopher Wilson May, 1978

Albuquerque Historic Landmarks Survey



#2

French House, 1315 Las Lomas N.E.
Spruce Park Historic District
Albuquerque, New Mexico

Built 1928-29
View from south

Christopher Wilson, May, 1978
Albuquerque Historic Landmarks Survey



#3

Scheer House, 1320 Las Lomas NE
Spruce Park Historic District
Albuquerque, New Mexico

View from northeast

Mary Davis, July, 1980

Albuquerque Historic Landmarks Survey



Street scene, Las Lomas at Spruce
Spruce Park Historic District
Albuquerque, New Mexico

View looking southwest, Scheer House at
right center

Mary Davis, December, 1980

Albuquerque Historic Landmarks Survey



1221 Las Lomas N.E. Non-contributing
Spruce Park Historic District
Albuquerque, New Mexico

Built 1952

Mary Davis July, 1980

Albuquerque Historic Landmarks Survey



1310 Las Lomas N.E. Non-contributing
Spruce Park Historic District
Albuquerque, New Mexico

Built post 1950
Mary Davis July, 1980
Albuquerque Historic Landmarks Survey



611 Spruce NE non-contributing
Spruce Park Historic District
Albuquerque, New Mexico

Built c. 1945

Mary Davis October, 1980
Albuquerque Historic Landmarks Survey



616 Cedar N.E. Non-contributing
Spruce Park Historic District
Albuquerque, New Mexico

Built 1957

Kathleen Brooker July 1980

Albuquerque Historic Landmarks Survey



1200 Marquette Place NE non-contributing
Spruce Park Historic District
Albuquerque, New Mexico

Built c. 1976

Mary Davis December, 1980

Albuquerque Historic Landmarks Survey



1425 Roma N.E. Non-contributing
Spruce Park Historic District
Albuquerque, New Mexico

Built c. 1965

Mary Davis September, 1980
Albuquerque Historic Landmarks Survey




1309 Roma NE Non-contributing
Spruce Park Historic District
Albuquerque, New Mexico

Built 1948

Mary Davis

August, 1980

Albuquerque Historic Landmarks Survey



1629 Roma NE non-contributing
Spruce Park Historic District
Albuquerque, New Mexico

Built c. 1950

Mary Davis August, 1980

Albuquerque Historic Landmarks Survey



1612 Roma NE non-contributing
Spruce Park Historic District
Albuquerque, New Mexico

Built c. 1948

Mary Davis August, 1980

Albuquerque Historic Landmarks Survey



416 Sycamore NE non-contributing
Spruce Park Historic District
Albuquerque, New Mexico

Built c. 1976

Mary Davis December, 1980
Albuquerque Historic Landmarks Survey



Street view, University Blvd. & Las Lomas
Spruce Park Historic District
Albuquerque, New Mexico

View looking west from intersection
Mary Davis December, 1980
Albuquerque Historic Landmarks Survey



Street view, Las Lomas at Cedar
Spruce Park Historic District
Albuquerque, New Mexico
View looking west over Rio Grande valley
Mary Davis December, 1980
Albuquerque Historic Landmarks Survey



Street scene, Spruce Street
Spruce Park Historic District
Albuquerque, New Mexico

View looking southwest, Spruce Park at rear
Mary Davis December, 1980
Albuquerque Historic Landmarks Survey



Street scene, 400 block of Maple NE
Spruce Park Historic District
Albuquerque, New Mexico

View looking south

Mary Davis December, 1980
Albuquerque Historic Landmarks Survey



Street scene, Roma at Spruce Park
Spruce Park Historic District
Albuquerque, New Mexico

View looking west

Mary Davis December, 1980

Albuquerque Historic Landmarks Survey



Thygerson House, 1315 Marquette Pl.

NE (1936)

Spruce Park Historic District
Albuquerque, New Mexico

View from southeast

Mary Davis, April, 1981

Historic Landmarks Survey
of Albuquerque

15



K. L. House House, 1300 Marquette Pl. NE 13

Spruce Park Historic District

Albuquerque, New Mexico

Built 1936

View from northwest

Mary Davis December, 1980

Albuquerque Historic Landmarks Survey



K. L. House House, 1300 Marquette Pl. NE 13
Spruce Park Historic District
Albuquerque, New Mexico

Front entry

Mary Davis

August, 1980

Albuquerque Historic Landmarks Survey



Karr House, 1306 Marquette Pl. NE
Spruce Park Historic District
Albuquerque, New Mexico

View from north

John Norton, April 1981

Albuquerque Historic Landmarks

Survey

#14



Gladding House, 643 Cedar N.E.
Spruce Park Historic District
Albuquerque, New Mexico

#1

Built 1926

view of front entrance from east

Kathleen Brooker, Nov. 1979

Albuquerque Historic Landmarks Survey



French House, 1315 Las Lomas NE
Spruce Park Historic District
Albuquerque, New Mexico

View of east wing from northeast

Mary Davis, July, 1980
Albuquerque Historic Landmarks Survey




#2

French House, 1315 Las Lomas NE
Spruce Park Historic District
Albuquerque, New Mexico

View from east

Mary Davis, July, 1980

Albuquerque Historic Landmarks Survey



Scheer House, 1320 Las Lomas NE.

#3

Spruce Park Historic District

Albuquerque, New Mexico

detail of chimney

Christopher Wilson May, 1978

Albuquerque Historic Landmarks Survey



McAvoy House, 1401 Las Lomas NE

#4

Spruce Park Historic District

Albuquerque, New Mexico

built 1924

View from southwest

Mary Davis, July, 1980

Albuquerque Historic Landmarks Survey



Cheek House, 1406 Las Lomas NE
Spruce Park Historic District
Albuquerque, New Mexico

#5

Built 1926

View from north

Mary Davis, July, 1980

Albuquerque Historic Landmarks Survey



Cheek House, 1406 Las Lomas N.E. #5
Spruce Park Historic District
Albuquerque, New Mexico

front entry from north

Mary Davis, July, 1980
Albuquerque Historic Landmarks Survey



Berndston House, 1409 Las Lomas NE
Spruce Park Historic District
Albuquerque, New Mexico

#6

Built 1927

View from southeast

Mary Davis December, 1980

Albuquerque Historic Landmarks Survey



1409

Berndston House, 1409 Las Lomas NE #6
Spruce Park Historic District
Albuquerque, New Mexico

View of front entry from southeast

Mary Davis July, 1980
Albuquerque Historic Landmarks Survey



Woolston House, 1513 Las Lomas N.E. #8

Spruce Park Historic District

Albuquerque, New Mexico

Built 1924

View from south

Mary Davis, May, 1980

Albuquerque Historic Landmarks Survey



Woolston House, 1513 Las Lomas NE #8
Spruce Park Historic District
Albuquerque, New Mexico

front entry from south
Mary Davis May, 1980
Albuquerque Historic Landmarks Survey



Gaastra House, 1524 Las Lomas NE

#9

Spruce Park Historic District

Albuquerque, New Mexico

Built 1929

View from north

Mary Davis

December 1980

Albuquerque Historic Landmarks Survey



Gastra House, 1524 Las Lomas N.E. #9
Spruce Park Historic District
Albuquerque, New Mexico

View from northeast
Mary Davis July, 1980
Albuquerque Historic Landmarks Survey



Sweenhart House, 624 Cedar N.E. #10

Spruce Park Historic District

Albuquerque, New Mexico

View from west Built 1938

Kathleen Brooker August 1980

Albuquerque Historic Landmarks Survey



Strong House, 1501 Roma N.E.

#11

Spruce Park Historic District

Albuquerque, New Mexico

Built 1938

View from southwest

Kathleen Brooker September, 1980

Albuquerque Historic Landmarks Survey



Strong House, 1501 Roma N.E.
Spruce Park Historic District
Albuquerque, New Mexico

#11

Detail of gate to north courtyard

Kathleen Brooker September, 1980
Albuquerque Historic Landmarks Survey



Tessier House, 1517 Roma N.E.

#12

Spruce Park Historic District

Albuquerque, New Mexico

Built 1929

View from southwest

Mary Davis August, 1980

Albuquerque Historic Landmarks Survey



Tessier House, 1517 Roma N.E.
Spruce Park Historic District
Albuquerque, New Mexico

#12

Entry from southwest

Mary Davis August, 1980

Albuquerque Historic Landmarks Survey