



Name: Rumsey Farm

Location: Route 301, west of Middletown, DE

Photographer: Jean Athan

Date: 1977

Location of Negatives: ~~Div. of Hist. & Cultural Affairs,~~
BUREAU of Archaeology & Historic Preserv., Dover, DE

Description: Facade which faces south.

Photograph Number: 1811

N-113 New Castle
County

OCT 31 1977

MAR 29 1978



Name: Rumsey Farm

Location: Route 301, west of Middletown, DE

Photographer: Jean Athan

Date: 1977

Location of Negative: Div. of Hist. & Cult. Affairs,
Bureau of Archaeology & Hist. Preserv., Dover, DE

Description: Detail of front door and porch

Photograph Number: 2811

N-113

OCT 31 1977

New Castle County

MAR 30 1978



Name: Rumsey Farm

Location: Route 301, west of Middletown, DE

Photographer: Jean Athan

Date: 1977

Location of Negative: Div. of Hist. & Cult. Affairs.

Bureau of Archaeology & Hist. Preserv., Dover, DE

Description: North wall and wing

Photograph Number: 3811

N-113

New Castle County

MAR 30 1978

OCT 31 1977



Name: Rumsey Farm

Location: Route 301, west of Middletown, DE

Photographer: Jean Athan

Date: 1977

Location of ~~Negative~~ Div. of Hist. & Cult. Affairs,
Bureau of Archaeology & Hist. Preserv., Dover, DE

Description: Detail of rear porch.

Photograph Number: 4 gll

OCT 31 1977

N-113

NEW Castle County

MAR 30 1978



Name: **Rumsey Farm**

Location: **Route 301, west of Middletown, DE**

Photographer: **Jean Athan**

Date: **1977**

Location of Negative: **Div. of Hist. & Cult. Affairs,
Bureau of Archaeology & Hist. Preserv., Dover, DE**

Description: **East wall of wing with porch**

Photograph Number: **5 811**

N-113

New Castle County OCT 31 1977

MAR 30 1978



Name: Rumsey Farm

Location: Route 301, west of Middletown, DE

Photographer: Jean Athan

Date: 1977

Location of Negative: Div. of Hist. & Cult. Affairs,
Bureau of Archaeology & Hist. Preserv., Dover, DE

Description:

Staircase in central stairhall

Photograph Number: 694

N-113

New Castle County

OCT 31 1977

MAR 30 1978



Name: Rumsey Farm

Location: Route 301, west of Middletown, DE

Photographer: Jean Athan

Date: 1977

Location of ~~Negative~~ Div. of Hist. & Cult. Affairs.
Bureau of Archaeology & Hist. Preserv., Dover, DE

Description:

Architrave common to all doors and windows
in the parlor on the west side of the central
stairhall.

Photograph Number 7 of 11

N-113

New Castle County OCT 31 1977

MAR 30 1978



Name: Rumsey Farm

Location: Route 301, west of Middletown, DE

Photographer: Jean Athan

Date: 1977

Location of Negatives: Div. of Hist. & Cult. Affairs,
Bureau of Archaeology & Hist. Preserv., Dover, DE

Description:

Detail of parlor door showing reeding on its
edge.

Photograph Number:

N-113

8 1/2"

OCT 31 1977

New Castle County

MAR 30 1978



Name: Rumsey Farm

Location: Route 301, west of Middletown, DE

Photographer: Jean Athan

Date: 1977

Location of Negatives: Div. of Hist. & Cult. Affairs,
Bureau of Archaeology & Hist. Preserv., Dover, DE

Description: Parlor marble mantle

Photograph Number: 9 g 11

N-113 NEW CASTLE COUNTY

OCT 31 1977

MAR 30 1978



Name: Rumsey Farm

Location: Route 301, west of Middletown, DE

Photographer: Jean Athan

Date: 1977

Location of Negative: Div. of Hist. & Cult. Affairs,
Bureau of Archaeology & Hist. Preserv., Dover, DE

Description:

Marble mantle from room in southeast corner
of the house.

Photograph Number: 10 of 11

N-113

NEW CASTLE County

OCT 31 1977

MAR 30 1978

PROPERTY OF THE NATIONAL REGISTER



Name: Rumsey Farm

Location: Route 301, west of Middletown, DE

Photographer: Jean Athan

Date: 1977

Location of Negative: Div. of Hist. & Cult. Affairs,
Bureau of Archaeology & Hist. Preserv., Dover, DE

Description:
Door to rear wing.

Photograph Number: 11 g''

N-113

New Castle County OCT 31 1977

MAR 30 1978