

East Providence Multiple Resource Area/1/51

Rumford Historic District East Providence, R.I.

Photographer: Robert O. Jones

Date: December 1979

Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, R.I.

General view facing southeast along Pawtucket Avenue, showing (1. to r.) the Bridgham Memorial Library, the First Baptist Church Parsonage, and the First Baptist Church.

Photo #1.

MM 58 1080



East Providence Multiple Resource Area/2/51/

Rumford Historic District East Providence, R.I.

s 1/01 28 1980

Photographer: Robert O. Jones Date: December 1979

Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, R.I.

View facing east showing (1. to r.) houses at 292-294 and 298 Pleasant Street.

Photo #2



East Providence Multiple Resource Area/3/51

Rumford Historic District East Providence, R.I.

Photographer: Robert O. Jones Date: December 1979


c 0. Jones 28 1980

Negative filed at:

Rhode Island Historical Preservation Commission 150 Benefit Street Providence, R.I.

View facing southeast along Pleasant Street, showing (1. to r.) the house at 338 Pleasant Street and the Thomas Aspinwall House at 344 Pleasant Street.

Photo #3.



East Providence Multiple Resource Area/4/51

First Baptist Church, Rumford Historic District East Providence, R.I.

Photographer: Robert O. Jones Date: December 1979

Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, R.I.

View of the facade facing northwest.

Photo #4.



East Providence Multiple Resource Area/5/51

Nathaniel Judkins House, Rumford Historic District East Providence, R.I.

Photographer: Warren Jagger

Date: January 1980

1 28 100

of By 100


Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, R.I.

General view of exterior facing east.

Photo #5.



East Providence Multiple Resource Area/6/51

House at 1527 Pawtucket Avenue, Rumford Historic District East Providence, R.I.

Photographer: Robert O. Jones Date: December 1979

NOV 28 1980 Negative filed at: Rhode Island Historical Preservation Commission

150 Benefit Street Providence, R.I.

General view of exterior facing north.

Photo #6.



East Providence Multiple Resource Area/7/51

Phanuel Bishop House, Rumford Historic District East Providence, R.I.

Photographer: Robert O. Jones Date: December 1979

NON 58

Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, R.I.

General view of exterior facing west.

Photo #7.



East Providence Multiple Resource Area/8/51

Lemuel Brown House, Hunts Mills Rumford Historic District East Providence, R.I.

Photographer: Warren Jagger Date: January 1980

May 58 1880 Negative filed at: Rhode Island Historical

Preservation Commission 150 Benefit Street Providence, R.I.

General view of exterior facing northwest

Photo #8.



East Providence Multiple Resource Area/9/51

John Hunt, Jr. House, Hunts Mills 101 28 1080 PB1 2 100 Rumford Historic District East Providence, R.I.

Photographer: Warren Jagger

Date: January 1980

Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, R.I.

General view of exterior facing northwest

Photo #9.



East Providence Multiple Resource Area/10/51

Pumping Station, Hunts Mills Rumford Historic District East Providence, R.I.

Photographer: Warren Jagger January 1980

NOV 28 1980

Negative filed at:

Rhode Island Historical Preservation Commission 150 Benefit Street Providence, R.I.

General view of exterior facing west

Photo #10.