



1. Sutton Farm
2. Shelburne, Chittenden County, Vermont
3. Deborah Noble
4. April 2004
5. VT. Division for Historic Preservation
6. Sutton Farm: property and buildings, looking southwest to Adirondacks
7. #1



1. Sutton Farm
2. Shelburne, Chittenden County, Vermont
3. Deborah Noble
4. April 2004
5. VT Division for Historic Preservation
6. Sutton Farm: buildings and structures a, b, d, f, g, looking southwest
4. #2



1. Sutton Farm
2. Shelburne, Chittenden County, Vermont
3. Deborah Noble
4. April 2004
5. VT Division for Historic Preservation
6. Sutton farmhouse (a) and garage/equipment shed (b), east facade, looking west
7. #3



1. Sutton Farm
2. Shelburne, Chittenden County, VT
3. Deborah Noble
4. April 2004
5. VT. Division for Historic Preservation
6. Sutton Farm: south and west facades of poultry house (c), garage/equipment shed (b) and farmhouse (a), looking northeast
7. #4





1. Sutton Farm
2. Shelburne, Chittenden County, VT
3. Deborah Noble
4. April 2004
5. VT Division for Historic Preservation
6. Sutton Farm: north and west facades of barn (d), silos (g+f), looking southeast
7. #5



1. Sutton Farm
2. Shelburne, Chittenden County, VT
3. Deborah Noble
4. April 2004
5. VT Division for Historic Preservation
6. Sutton Farm: south and west facades of barn (d), silos (e, f, g) and mobile home (h),  
looking northeast
7. #6