



La Glorieta, 1801 Central Ave. NW (10)  
Downtown Neighborhoods Area  
Albuquerque, New Mexico

Chris Wilson, 1979  
Albuquerque Historic Landmarks Survey

Looking NE PHOTO # 1

**OCT 20 1980**

*Albuquerque Downtown Neighborhood  
Multiple Res. area/Bernalillo Co.*



Albuquerque Downtown Neighborhoods Multiple Resource Area/Bernalillo Co.

La Glorieta, 1801 Central NW (10)

Downtown Neighborhoods Area  
Albuquerque, New Mexico

1930's photograph - placita  
looking north.

Photo # 2

photographer unknown  
Albuquerque Museum

**OCT 4 0 1980**



La Glorieta, 1801 Central Avenue NW (10)  
Downtown Neighborhoods Area  
Albuquerque, New Mexico

East Facade

photo # 3

Richard Khanlian, 1976  
Albuquerque Historic Landmarks Survey

OCT 20 1980

Albuquerque Downtown neighborhood  
Multiple Resource Area / Bernalillo Co.



Albuquerque Downtown Neighborhoods Multiple Resource Area/Bernalillo Co.

La Glorieta, 1801 Central Avenue NW (10)  
Downtown Neighborhoods Area  
Albuquerque, New Mexico photo #4

South Entry Door

Christopher Wilson, 1979  
Albuquerque Historic Landmarks Survey

OCT 20 1980





La Glorieta, 1801 Central NW  
Albuquerque, New Mexico

#5

View of building from southeast

Mary Davis, December, 1980  
Albuquerque Historic Landmarks Survey



La Glorieta, 1801 Central NW #6  
Albuquerque, New Mexico

Lilac walk leading to south entrance

Mary Davis, December, 1980  
Historic Landmarks Survey of Albuquerque



La Glorieta, 1801 Central NW #7  
Albuquerque, New Mexico

Front facade and arbor portal from SE

Christopher Wilson, June, 1978  
Historic Landmarks Survey of Albuquerque



La Glorieta, 1801 Central NW  
Albuquerque, New Mexico

#8

West wall from iW

Mary Davis, 1980

Albuquerque Historic Landmarks Survey





La Glorieta, 1801 Central NW  
Albuquerque, New Mexico

#9

Northeast corner of placita

Mary Davis, 1980

Albuquerque Historic Landmarks Survey



La Glorieta, 1801 Central NW  
Albuquerque, New Mexico

#10

Southwest corner, placita

Mary Davis, 1980

Albuquerque Historic Landmarks Survey



La Glorieta, 1801 Central NW

#11

Albuquerque, New Mexico

Southeast corner, placita

Mary Davis, 1980

Albuquerque Historic Landmarks Survey



La Glorieta, 1801 Central NW #12  
Albuquerque, New Mexico

East wall, placita (from southwest)

Mary Davis, 1980  
Albuquerque Historic Landmarks Survey