

photographer facing south

Photographer: James R. Lockhart
Negative: On file at the Georgia Department
of Natural Resources
Date: December 1986
1 of 9: Main Entrance to original classroom

building with "SCS" cartouche above the door;



Photographer: James R. Lockhart
Negative: On file at the Georgia Department
of Natural Resources
Date: December 1986
2 of 9: Main Entrance and additions to the

east of it; photographer facing southeast



Statenville, Echols County, Georgia
Photographer: James R. Lockhart
Negative: One file at the Georgia Department
of Natural Resources

STATENVILLE CONSOLIDATED SCHOOL

Date: December 1986
3 of 9: Main Entrance on left with auditorium wing on the right; photographer facing southwest



Photographer: James R. Lockhart Negative: On file at the Georgia Department of Natural Resources Date: December 1986 4 of 9: Auditorium entrance; photographer facing east



Photographer: James R. Lockhart

Negative: On file with the Georgia Department of Natural Resources Date: December 1986 5 of 9: Rear of original classroom building with additions. Walkway on left connects to property outside of the nominated area; photographer facing northwest



Photographer: James R. Lockhart

building photographer facing south

Negative: On file at the Georgia Department of Natural Resources Date: December 1986 6 of 9: Central hall of original classroom



Photographer: James R. Lockhart Negative: On file at the Georgia Department of Natural Resources Date: December 1986 7 of 9: Typical classroom in original classroom building; photographer facing west



Photographer: James R. Lockhart Negative: On file at the Georgia Department of Natural Resources Date: December 1986 8 of 9: Interior of auditorium, facing the stage; photographer facing east



entrance/exit; photographer facing west

Photographer: James R. Lockhart
Negative: On file with the Georgia Department
of Natural Resources
Date: December 1986
9 of 9: Interior of auditorium, facing the