

Charlotte Schneider Kentucky Heritage Commission Frankfort, Kentucky October 1978 MAR 28 1979

FEB 1 3 1979 Photo 1. Main facade of house taken from southeast.



## MAR 28 1979

Charlotte Schneider Kentucky Heritage Commission Frankfort, Kentucky October 1978

#### FEB 1 3 1979

Photo 2. Detail of transom and door frame on rear of house.



FEB 1 3 1979

Charlotte Schneider Kentucky Heritage Commission Frankfort, Kentucky October 1978

# MAR 28 1979

Photo 3. View of rear of house taken from west.



### MAR 28 1979

Charlotte Schneider Kentucky Heritage Commission Frankfort, Kentucky October 1978

> Photo 4. Mantle in southwest parlor.



#### MAR 28 1979

Charlotte Schneider Kentucky Heritage Commission Frankfort, Kentucky October 1978

Photo 5. Interior detail of mantle in second floor northeast bedroom.

1 8 1 3 1979



### MAR 28 1979

Charlotte Schneider Kentucky Heritage Commission Frankfort, Kentucky October 1978

FEB 1 3 1979

Photo 6. Interior showing front entrance.



FEB 1 3 1979

Charlotte Schneider Kentucky Heritage Commission Frankfort, Kentucky October 1978 MAR 28 1979

Photo 7. View of single-pen log house taken from north. Note unusual length.



FEB 1 3 1979

Charlotte Schneider Kentucky Heritage Commission Frankfort, Kentucky October 1973

## MAR 28 1979

Photo 3. View of slave quarters taken from east.



#### FEB 1 3 1979

Charlotte Schneider Kentucky Heritage Commission Frankfort, Kentucky October 1973

### MAR 28 1979

Photo 9. View of outbuildings north of main residence including singlepen log house.