


```
Kienlen-Harbeck Building
147 SW G St.
Grants Pass, Josephine County, Oregon 97526
Date of Photograph: 1981
Negative: Kay Atwood
          102 So. Pioneer
          Ashland, Oregon 97520
View: North elevation and facade
1 of 13
```



Kienlen-Harbeck Building 147 S.W. G Street Grants Pass. Josephine County. Oregon 97526 Date of Photograph: 1981 Negative: Kay Atwood 102 So. Pioneer Ashland, Oregon 97520 View: West elevation



Kienlen-Harbeck Building 147 S.W. G Street Grants Pass, Josephine County, Oregon 97526 Date of Photograph: 1981 Negative: Kay Atwood 102 So. Pioneer Ashland, Oregon 97520

View: South and rear elevation



Kienlen-Harbeck Building
147 S.W. G Street
Grants Pass, Josephine County, Oregon
Date of Photograph: 1981
Negative: Kay Atwood
102 So. Pioneer

Ashland, Oregon 97520


View: North elevation; facade View of upper story



147 S.W. G Street Grants Pass, Josephine County, Oregon Date of Photograph: 1981 Negative: Kay Atwood 102 So. Pioneer Ashland, Oregon 97520 View: Northwest corner of building view of cornice and upper level

decorative elements

Kienlen-Harbeck Building




Kienlen-Harbeck Building 147 S.W. G Street Grants Pass, Josephine County, Oregon Date of Photograph: 1981 Negative: Kay Atwood 102 So. Pioneer Ashland, Oregon 97520 View: Pedestal of cast iron column North elevation and facade 6 of 13



Kienlen-Harbeck Building 147 S.W. G Street Grants Pass, Josephine County, Oregon Date of Photograph: c. 1910 Negative: Josephine Co. Historical Society Grants Pass, Oregon 97526 View: Front entrance to building on corner of G and 5th Streets.



```
Kienlen-Harbeck Building
147 S.W. G Street
Grants Pass, Oregon, Josephine County
Date of Photograph: 1981
Negative: Kay Atwood
           102 So. Pioneer
           Ashland, Oregon 97520
View: G Street between 4th and 6th
       sts. Approximate view of
       blocks as shown in Photograph # 8
       9 of 13
```



Kienlen-Harbeck Building 147 S.W. G Street Grants Pass, Josephine County, Oregon Date of Photograph: c. 1900 -1902 Negative: Josephine County Historical Soc.

Grants Pass, Oregon 97526

View: G Street between 4th and 6th Sts.

Taken after 1900 and before 1902

Fire destroyed wooden buildings
on these blocks in September, 1899



```
Kienlen-Harbeck Building
147 S.W. G Street
Grants Pass, Oregon, Josephine County
Date of Photograph: 1981
Negative: Kay Atwood
          102 So. Pioneer St.
          Ashland, Oregon 97520
View: Interior: Storage space of
       former meat market. upper floor
```



```
Kienlen-Harbeck Building
147 S.W. G Streets
Grants Pass, Josephine County, Oregon
Date of Photograph: 1981
Negative: Kay Atwood
          102 So. Pioneer
          Ashland, Oregon 97520
View: Interior: Wall and curtain.
       former renter's room, upper
       level
11 of 13
```

HOUSE GUESTS ONLY

```
Kienlen-Harbeck Building
147 S.W. G Street
Grants Pass. Jospenine County. Oregon
Date of Photograph: 1981
Negative: Kay Atwood
           102 So. Pioneer
           Ashland, Oregon 97520
View: Interior: Hall to rooms.
       upper level
12 of 13
```



Kienlen-Harbeck Building 147 S.W. G Street Grants Pass, Josephine County, Oregon Date of Photograph: 1981 Negative: Kay Atwood 102 So. Pioneer Ashland, Oregon 97520 View: Interior: View of elevator cage and mechanism