




Facade facing Southeast, D.C.
Department of Recreation field
office, 750 Park Road, N.W.
Washington, D.C., 1985




10TH PRECINCT
POLICE STATION

Major decorative elements of facade including rectangular building name with fasces surround topped by an oculus with floral motif. D.C. Department of Recreation field offices 750 Park Road, N.W., Washington, D.C., 1985



Detail of bracketted cornice
with twisted rope above and egg
and dart moldings below brackets.
Band of patterned brick work be-
neath cornice, window lintel with
and egg and dart molding. D.C.
Department of Recreation field
offices 750 Park Road, N.W.
Washington, D.C., 1985




View of Iron Door in Basement
Cell Block, 750 Park Road, N.W.
Washington, D.C., 1985



Carved Stair Post, First Floor,
750 Park Road, N.W., Washington,
D.C., 1985.



Carved Stair Post, First Floor,
750 Park Road, N.W. Washington,
D.C., 1985



Oculus Second floor, front
elevation, D.C. Department of
Recreation, 750 Park Road, N.W.
Washington, D.C., 1985



10th Precinct Station House
Washington, D.C.

Martha Bowers, Photographer

August 2, 1984

Negative on file at Louis Berger & Associates, Inc.

Cultural Resource Group

100 Halsted Street

East Orange, N.J. 07019

View facing south of alley west of building; note
brickwork on first floor exterior and decorative
keystone above window.

2 of 4