



| NameBasye_House                           |
|---|
| Location Lexington, KY.                   |
| Photographer M. Anne Browne               |
| Date Taken7/87                            |
| Negative Location The Historic Commission |
| View_ facade of house, northeast corner   |
|   |
| Photo # 1                                 |





| Name Basye House                          |
|---|
| Location Lexington, KY.                   |
| Photographer M. Anne Browne               |
| Date Taken7/87                            |
| Negative Location The Historic Commission |
| View_ east facade of house                |
|   |
| Photo # 2                                 |





Photo # 3

| Name Basye House  |
|---|
| Location Lexington, KY.   |
| Photographer M. Anne Browne   |
| Date Taken7/87  |
| Negative Location The Historic Commission   |
| View northern veranda, northeast corner of  |
| house   |
| Negative Location The Historic Commission  View northern veranda, northeast corner of |





Basye House Name Location\_ Lexington, KY. Photographer M. Anne Browne Date Taken 7/87 Negative Location The Historic Commission View southeast corner - note: brackets, hoods and altered columns on veranda Photo # 4





| NameBasye House                            |
|--|
| Location Lexington, KY.                    |
| Photographer M. Anne Browne                |
| Date Taken7/87                             |
| Negative Location The Historic Commission  |
| View Original service wing & frame infill, |
| north elevation                            |
| Photo # 5                                  |





| Name_ Basye House                         |
|---|
| Location Lexington, KY.                   |
| Photographer M. Anne Browne               |
| Date Taken7/87                            |
| Negative Location The Historic Commission |
| View_ front door detail                   |

Photo # 6





| Name     | The Bas | ye House |         |       |      |        |
|----------|---------|----------|---------|-------|------|--------|
| Location | Lexin   | gton, KY | •       |       |      |        |
| Photogra | pher    | M. Anne  | Browne  |       | ,    |        |
| Date Tak | en      | 7/87     |         |       |      |        |
| Negative | Locati  | on The H | istoric | Commi | ssic | on     |
| View_no  | rthwest | corner:  | dining  | room  | and  | first- |
| story a  | ddition | (bath)   |         |       |      |        |
| Photo #  | 7       |          |         |       | 1    |        |





| Name Basye House                    |           |
|-------------------------------------|-----------|
| Location Lexington, KY.             |           |
| Photographer M. Anne Browne         |           |
| Date Taken7/87                      |           |
| Negative Location The Historic Comm | mission   |
| View_ fish-eye view of 2½-story sta | air-hall: |
| looking south                       |           |
| Photo # 8                           |           |





Basve House

| Name      | Dabje  | - 110 45 4 |       |         |           |
|-----------|--------|------------|-------|---------|-----------|
| Location_ | Lexi   | ngton,     | KY.   |         |           |
| Photograp | her    | M. Anr     | ne Br | owne    |           |
| Date Take |        |            |       |         |           |
| Negative  |        |            | Hist  | oric Co | mmission  |
| View_det  | ail of | stair      | and   | ceiling | medallion |
|           |        |            |       |         |           |
| Photo #   | 9      |            |       |         |           |





| Name basye nouse                          |  |  |  |  |  |  |
|---|--|--|--|--|--|--|
| Location Lexington, KY.                   |  |  |  |  |  |  |
| Photographer M. Anne Browne               |  |  |  |  |  |  |
| Date Taken7/87                            |  |  |  |  |  |  |
| Negative Location The Historic Commission |  |  |  |  |  |  |
| View detail of typical door and window    |  |  |  |  |  |  |
| trim (dining room)                        |  |  |  |  |  |  |
| Photo # 10                                |  |  |  |  |  |  |





| NameBas     | sye Hou | ıse   |      |       |       |        |
|-------------|---------|-------|------|-------|-------|--------|
| Location    | Lexing  | ton,  | KY.  |       |       |        |
| Photographe | er_M.   | Anne  | Brow | ne    |       |        |
| Date Taken  | 7/8     | 37    |      |       |       |        |
| Negative Lo | ocation | The   | Hist | coric | Commi | ssion  |
| View_detai. | ı of pa | arlor | and  | ha11  | trim  | (south |
| (parle      | or)     |       |      |       |       |        |
| Photo # 1.  | 1       |       |      |       |       | X      |





Photo #

| Name_ | Basye     | House                         | _ |
|-------|-----------|-------------------------------|---|
| Locat | ion_ Lex  | rington, KY.                  | _ |
| Photo | ographer_ | M. Anne Browne                |   |
| Date  | Taken     | 7/87                          | _ |
| Negat | ive Loca  | tion The Historic Commission  |   |
| View_ | windows   | in tower chamber (south side) |   |
|       | 2.5       |                               |   |