



Stanton Mill (Complex)

Garrett County, Maryland

February 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD

Overall view of complex: mill in foreground
c. 1900 warehouse bldg. to right; mill bldg.

1/23 in far background



Stanton Mill (Complex)

Garrett County, Maryland

1913, reprint 1982 (Courtesy of Mrs. Maxine
Broadwater, Grantsville, MD-glass plate neg)

Photo: Leo Beachy

Historic photograph of mill in 1913. Note
pickett fence and wooden forebay, now missing

2/23



Stanton Mill (Complex)

Garrett County, Maryland

1913, reprint 1982

Photo: Leo Beachy

Glass plate neg. (Courtesy of Mrs. Maxine
Broadwater, Grantsville, MD)

Closeup of #2/23 of mill in 1913

3/23



Stanton Mill (Complex)

Garrett County, Maryland

January 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD

View of mill building, with main (south)
facade and east gable end of c.1859 structure.

4/23

View from S.E.



Stanton Mill (Complex)

Garrett County, Maryland

January 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD

View of mill building with main (south) facade
and west gable end. Addition, c.1900 structure
to L.; c.1859 structure to R. View from SW 5/23



Stanton Mill (Complex)
Garrett County, Maryland

January 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD
Rear (north facade of mill, showing original
c.1859 section to L, c.1900 section to R.

6/23

View from N.



6
Stanton Mill (Complex)
Garrett County, Maryland
January 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD
Steel pipe linking concrete forebay to modified Francis turbine, basement of c.1859 section of mill. View looking S.

7/23



9


Stanton Mill (Complex)

Garrett County, Maryland

January 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD
View of first floor of c.1859 section of mill,
looking west showing c.1930 Buffalo Forge Co.
cracker and grader, storage bins, etc. 8/23



Stanton Mill (Complex)
Garrett County, Maryland

January 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD
View of c.1859 section of mill, northeast
corner of ceiling, showing remnants of power
train system. 9/23



Stanton Mill (Complex)
Garrett County, Maryland
January 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD
Southwest corner of c.1859 section of mill,
second floor looking west, view shows heavy
timber framing, original exterior hoist
system now incorporated into c.1900 section.

10/23



Stanton Mill (Complex)

Garrett County, Maryland

January 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD

Second floor of c.1859 section of mill, showing Wolf Co. (Chambersburg, PA) "Gyrator" floor

11/23

separator



Stanton Mill (Complex)

Garrett County, Maryland


January 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD
Second floor of c1859 section of mill, looking
east. View shows S. Howe & Co. Eureka brand
dustless separator machinery (for cleaning

and scouring buckwheat), and linkage to power
train.

12/23



Stanton Mill (Complex)

Garrett County, Maryland

January 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD

Second S. Howe and Co. Eureka brand dustless

separator, stored in southeast corner of

second floor. c.1859 section of mill



Stanton Mill (Complex)
Garrett County, Maryland

January 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD

Attic of c.1859 section of mill, showing
stored scoop belts from elevators. View

looking E. 14/23

13




Stanton Mill (Complex)
Garrett County, Maryland

January 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD
Attic of c. 1859 section of mill, showing
post/purlin support system for roof (background
elevator head (foreground)). View looks W. 15/23



Stanton Mill (Complex)

Garrett County, Maryland

January 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD

View of cylindrical separator, and head of
elevator, attic of c.1859 section of mill.

16/23

View looks N.



STANTONS MILL

Stanton Mill (Complex)
Garrett County, Maryland

January 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD
View of c.1900 warehouse building, showing
main (north) facade and gable end. View from N.
17/23



Stanton Mill (Complex)
Garrett County, Maryland

January 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD
View of 1817 National Road single span stone
arch bridge, with mill in background.

18/23

STANTONS MILL



Stanton Mill (Complex)
Garrett County, Maryland

January 1982

Photo: Mark Edwards

Neg: Maryland Historical Trust, Annapolis, MD
View of stone wall to west of stone arch
bridge, showing buhr millstones incorporated
19/23 into face. View looks SE.



THE DAM
GRANTSVILLE, MO.

Stanton Mill (Complex)

Garrett County, Maryland

1916, reprinted February 1982

Photo: Leo Beachy

Neg: Courtesy of Mrs. Maxine Bradwater,
Grantsville, MD

View of dam in 1916, looking SW

20/23



Stanton Mill (Complex)
Garrett County, Maryland
January 1982
Photo: Mark Edwards
Neg: Maryland Historical Trust, Annapolis, MD
View of remains of timber crib dam and stone
facing, east end of dam. View looking E.
21/23

12" x 3" 1-1/2" STEEL OVERSHOT WATER WHEEL GEARING, SHIFTER & C.



E. J. STANTON & SON, GRANTSVILLE, MD.

HANOVER FOUNDRY & MACHINE CO., HANOVER, PA.

Scale 1/4" = 1"

WHEEL 1/2" EBB

MAY 14 1888



Stanton Mill (Complex)
Garrett County, Maryland
Blueprint dated May 14, 1898, of steel over-
shot water wheel manufactured by Hanover
Foundary and Machine Co., Hanover Pennsylvania

22/23

Stanton Mill (Complex)
Garrett County, Maryland
Blueprint dated July 3, 1928, showing plans
for a 24" Fitz-Burnham Water Wheel
manufactured by Fitz Water Wheel Company,
Hanover, Pennsylvania

23/23