



Photograph 1

David Welch House, Litchfield, Ct.

Allan E. Raymond photo Jan., 1983

Neg. on file Ct. Historical Commission

Locations shot, facing west on Potash Road towards
Trinity Church at the head of Milton Green, former
Guild Tavern, and the Milton Congregational Church.



Photograph 2

David Welch House, Litchfield, Ct.

Allan E. Raymond photo, Jan. 1983

Neg. on file, Ct. Historical Commission

Front elevation, looking north. Shows unbalanced facade with lights over main door and Dutch door to right leading to former store addition.



Photograph 3

David Welch House, Litchfield, Ct.

Allan E. Raymond photo, Jan., 1983

Neg. on file, Ct. Historical Commission

Rear elevation, looking woutheast, showing 1792 kitchen
and pantry, extended by modern kitchen and sheds.



Photograph 4

David Welch House, Litchfield, Ct.

Allan E. Raymond photo, Jan., 1983

Neg. on file, Ct. Historical Commission

East elevation, looking west.



Photograph 5

David Welch House, Litchfield, Ct.

Allan E. Raymond photo, Jan., 1983

Neg. on file, Ct. Historical Commission

West elevation, looking east.



Photograph 6

David Welch House, Litchfield, Ct.

Ben Schnall photo, Sept., 1969

Neg. on file, Ct. Historical Commission

Master bedroom, looking northwest.



Photograph 7

David Welch House, Litchfield, Ct.

Ben Schnall photo, Sept., 1969

Living room, facing west, showing vertical panelling and finished trim. Wide, white oak, random-width flooring is original.



Photograph 8

David Welch House, Litchfield, Ct.

Ben Schnall photo, Sept., 1969. Neg. on file Ct. Hist. Commission.

Study, looking southwest. Modern bookcases shorten the original houseroom, which ran the length of the original house. Some of the books belonged to early owners. Fireplace was built outside the original chimney of massive masonry.



Photograph 9

David Welch House, Litchfield, Ct.

Ben Schnall Photo, Sept., 1969

Neg. on file, Ct. Historical Commission.

Living room, looking northeast. Counter of early store stood where sofa sits. Franklin stove was placed in the house at an early date, and is one of the first models.



Photograph 10

David Welch House, Litchfield, Ct.

Ben Schnall photo, Sept., 1969

Neg. on file, Ct. Historical Commission

Living room, looking southeast. Dutch doors make a second front entrance. China closet and adjacent blanket chest are original.



Photograph 11

David Welch House, Litchfield, Ct.

Ben Schnall photo, Sept., 1969

Neg. on file, Ct. Historical Commission

Dining room, looking east. Shows size of lintel over fireplace and ship-stepped beams, narrower at base. Panelling on walls to right is horizontal. Oven is outside fireplace with an ashpit below. Tinder box is behind bed warmer above lintel.




Photograph 12

David Welch House, Litchfield, Ct.

Ben Schnall photo, Sept., 1969

Neg. on file, Ct. Historical Commission

Dining room, looking southwest. Shows manner in which addition joins the older section of the house (to the right) and the east wing (in the left half of the picture.)



Photograph 13

David Welch House, Litchfield, Ct.

Allan E. Raymond photo, Jan., 1983

Neg. on file, Ct. Historical Commission

Necessary house, looking northeast.



Photograph 14

David Welch House, Litchfield, Ct.

Allan E. Raymond photo, Jan., 1983

Neg. on file, Ct. Historical Commission

Lower barn and Main barn, looking north.