NATIONAL REGISTER OF HISTORIC PLACES NOMINATION, GLACIER NATIONAL PARK

REGION: Rocky Mountain PARK	/AREA NAME:	Glacier N	ational	Park PARK	NUMBER:	1430
STRUCTURE NAME: Scalplock Mounta	in Fire Look	out		STRUCTURE	NUMBER:	629
by trail connecting to Boundar Zone Easting Northing	Mountain; a y Trail near		nger Sta	GLE NAME: Ess tion RANGLE SCALE:	•	
UTM: 12 309165 5352655 CLASSIFICATION:			NUMBER	OF RESOURCES	:	
	EGORY:	CONT		NONCONTRIBUT		
Private	x_ Building(s)	1		Buildi	ings
Public-Local	District				Sites	
Public-State x Public-Federal	Site Structure	-		-	Struct	
Mixed/private & public		-	1		Object TOTAL	: s
ARCHITECTURAL DESCRIPTION AND EVAL		-			IOIAL	
The Scalplock Mountain fire look		o-story, s	quare (1	4x14'), frame	building	with
a rolled asphalt pyramidal hip	roof and l'x	10" lapboa:	rd sidin	g. The struct	ture is se	et on
a rubblestone and concrete pad						
board-and-batten entry. The up						
pane windows and a catwalk wrap in good condition. This lookou						
10-ft. tower with catwalk. The						
Forest Service, was often modifi						
neers. The Scalplock Mountain		•			_	
workmanship and is significant						ζ.
HISTORICAL DEVELOPMENT AND EVALUAT				TRUCTION: 193		
Glacier National Park Superinter						i
prime lookout site in 1931 becau Valley and a large unseen area				-		
traversed by the Roosevelt High					•	
fact that many fires originated	•			•	-	
ability to view the entire travel corridor that forms the southwest boundary of the park						
became an administrative mandate						
the Flathead National Forest) as						
similar buildings constructed in						
early 1940s to protect park lands from the always critical threat of fire. A planned network of lookouts within the Park and on adjoining national forest lands allowed						
reciprocal surveillance of both areas. The series of lookouts in Glacier succeeded for						
many years in reducing the number of disastrous fires in the park. Today, air obser-						
vation allows a more comprehens:		-		_		
lookout almost entirely. The So	-			_		
illustrates an important aspect in Glacier National Park.	in the mana	gement and	conserva	ation of timbe	r resourc	:es
STATEMENT OF SIGNIFICANCE:						
The Scalplock Mountain fire look	kout is a si	gnificant	resource	both archited	cturally a	ınd
historically. It meets the elig		_			-	
Register of Historic Places und	er criteria	a and c.				
BIBLIOGRAPHIC REFERENCE:						_
¹ E.T. Scoyen to the Director, Na Buildings, Roads and Trails; Loc to November 1945, Glacier Nation	okout Statio	ns," File:	620-03	7, Part One Fr	com July l	
National Archives, Washington, 1	•					

NAME/TITLE: ORGANIZATION: Historical Research Associates, P.O. Box 7086, Missoula, MT 59807-7086

DATE: June 1984

FORM PREPARED BY:


86000363

CFR

United States Department of the InteriorNational Park Service

National Register of Historic Places Continuation Sheet

Scalplock Lookout (addendum), Flathead County, MT.



3. State/Federal Agency Certification		
As the designated authority under the National Historic Preservation meets the documentation standards for registering properties in the Part 60. In my opinion, the property X meets does not mee statewide _X locally. (See continuation sheet for additional Signature of certifying official/Title National Park Service State or Federal agency or bureau	e National Register of Historic Places and mo t the National Register Criteria. I recommend	ets the procedural and professional requirements set forth in 36
In my opinion, the property / megts does not meet th	ne National Register criteria.	
Signature of commenting or ether official Montana State Historic Preservation Office State or Federal agency and bureau		SFP 2 9 1995.
1. National Park Service Certification		
, hereby certify that this property is: entered in the National Register see continuation sheet determined eligible for the National Register see continuation sheet	Signature of the Keeper	Date of Action
determined not eligible for the National Register see continuation sheet		
removed from the National Register see continuation sheet		
other (explain) Additional Documentation Accepted	Grupm. Lapse	1/19/96

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number

7 Page 2

Scalplock Lookout (addendum), Flathead County, MT.

Building Interior

The Scalplock Lookout is listed in the National Register of Historic Places. Additional documentation is provided below for the purpose of describing and evaluating the interior for integrity and significance.

7. Narrative Description

Summary

Fire lookouts were generally constructed from standardized building packages, packed to the lookout site for assembly. Most were also constructed following the mid-1920s increase in lookout-construction appropriations and prior to the 1930s advent of aerial fire detection and suppression. This use of standard plans and the short construction period resulted in a remarkable degree of uniformity in interior design, not only in park lookouts but also in contemporaneous lookouts built on the forests of the USFS Northern Region. Paneled or vertical-plank doors (like the windows, paired with full-length "storms") provided access. In a classic case of design following function, large multi-light awning windows dominated all four elevations; painted 2" to 4" tongue-and-groove planks covered the small expanse of exposed interior wall. Floors were generally finished with painted 3-inch to 6-inch softwood. Fixed furnishings included the critical and centrally located fire finders, a wood-burning stove, a small cot, a wood table and chair(s), and wall-mounted cupboards located above the window banks, near the ceilings. Ceilings were either open/exposed truss or, if dropped, finished with painted tongue-and-groove planks and containing a hinged door leading to the "attic" storage space. Food and equipment storage areas in the "basement" were unfinished and accessed by vertical-board or paneled wood doors.

Scalplock Lookout (#629), 1931

As befits its function, pairs of large two-light windows dominate the interior of this small building. Three-inch floorboards, painted grey and paired with narrow 1" quarter-round baseboards, cover the floors. The same 3" planks (either shiplap or tongue-and-groove), laid horizontally, cover the walls and ceiling. Plywood "shutters" are centered above each central window; held in place by swivel latches these remove to reveal screened vents. Each corner, above the windows, has been fitted with a corner shelf. A trap door, also constructed of 3" planks, provides access to the attic storage space. Two-inch boards, painted white, frame all windows and the three-panel/one-light exterior door.

Fixed furnishings include two white tables and two white chairs; a bedframe; mattresses; modern propane refrigerator; four cabinets constructed of the same 3" tongue-and-groove planks used on the walls, ceiling, and floors; a solar powered radio; and the centrally located Osborne fire finder, mounted on a grey metal stand.

The basement storage area, created by the elevated construction of the primary component and accessed through a board-and-batten door, is unfinished, with dirt floors and exposed frame walls and ceiling. Open shelves and the floor space are littered with tools, propane tanks, and miscellaneous equipment.

United States Department of the InteriorNational Park Service

National Register of Historic Places Continuation Sheet

Section number

8, Photographs

Page 3

Scalplock Lookout (addendum), Flathead County, MT.

8. Statement of Significance

The interior is unmodified and contributes to the building's significance.

Photographs

1) Photographer:

Jason Wilmot

2) Date of Photographs:

September 1993

3) Location of Negatives:

National Park Service, RMR-RC, Denver, CO.

PHOTO NUMBER	BUILDING NAME AND NUMBER	DESCRIPTION
1	Scalplock Lookout (#629)	Interior-detail of cabinet unit
2	Scalplock Lookout (#629)	Interior