Form KHC1985-2

Page 1 of 3 pages

KENTUCKY HISTORIC RESOURCES Individual Inventory Form

40 NOV 1 5 1988

Resource # 124 Shelby County

| 1. | Name of Resource: |
|-----|---|
| | Brackett Owen House |
| 2. | Original Owner: |
| | Brackett Owen |
| 3. | Other Names: |
| | None |
| 4. | Prehistoric Site x Building Object |
| | Historic Site Structure Other |
| 5. | Location: |
| | North side of Hooper Station Rd., 1/4 mile |
| | east of KY 53 |
| 6. | Owner's Name: |
| | |
| · | G. W. Thomas [P] |
| 7. | Owner's Address: |
| | ۵ - |
| | Rte. 6, Shelbyville, KY 40065 |
| 8. | |
| 9. | Recognition & Date: |
| | Nat.Landmark Local Landmark |
| | Nat.Register HABS/HAER |
| | Highway Marker KY Inventory 8-15-80 |
| | KY Landmark Certificate |
| 10. | N.R.Status & Date: |
| 11. | N.R.Group: |
| | District Name: [] |
| | Mult.Resource Area: Shelby County [] |
| | Thematic Name: [] |
| 12. | Historical Theme: |
| | Primary: Exploration/Settlement [140] |
| | Secondary: [] |
| | Other: [] |
| 13. | Statement of Significance: |
| Th | e property is significant under Criterion C as an |
| | tact example of the two-story hall/parlor plan |

e of the two-story hall/parlor plan constructed in brick. The period of significance (1800-24) for the dwelling straddles two eras: early settlement (1780-1810) and early 19th century (1810-1840). Six buildings with similar forms were

identified in Shelby County (continued) [C] 14. History:

House appears to have[^]built in the first quarter of the 19th century and is recorded as the residence of Brackett Owen who emigrated to Shelby County area in 1785. Owen's Station southeast of present-day Shelbyville was the third major station to be established in the region, following that of Squire Boone (ca. 1781) and Robert Tyler (1783). The first session of the newly created county court was held in Brackett Owen's house on October 15, 1792.

15. Source of historical information and/or contact person:

| 16. Date: | |
|---|---|
| Original Building | 1800-24 [8] |
| Addition | [] |
| 17. Style: | |
| | [] |
| Settlement Vernacu | lar [2V] |
| 18. Architect/Builder: | |
| IInknown | |
| 19. No. of Stories: 2 | [2.0] |
| 20. Original Floor Plan: | |
| Hall-parlor (two-ro | oom) [HP] |
| 21. Single Pile x Do | buble Pile N.A. |
| 21. Single File X Do 22. Roof Form & Mater | |
| | |
| Gable, asphalt shi 23. Structural Material: | ngre not Original |
| | |
| Brick | |
| 24. Exterior Material: | |
| Brick, Flemish bor 25. Foundation Material | nd facade [B] |
| | |
| Stone, coursed rub | ble [S] |
| 26. Major Alterations: | None |
| | |
| Moved/Rebuilt | Other |
| x Additions | Uiner |
| x Additions 27. Special Features: | Ulner |
| x Additions 27. Special Features: None | |
| x Additions 27. Special Features: None 28. Outbuildings: | Uiner |
| x Additions 27. Special Features: None 28. Outbuildings: Non-contributing | [NÇ] |
| x Additions 27. Special Features: None 28. Outbuildings: Non-contributing 29. Original Function: | [NÇ_] |
| x Additions 27. Special Features: None 28. Outbuildings: Non-contributing 29. Original Function: Residential/Domes | [NÇ_] |
| x Additions 27. Special Features: None 28. Outbuildings: Non-contributing 29. Original Function: | |
| x Additions 27. Special Features: None 28. Outbuildings: Non-contributing 29. Original Function: Residential/Domes 30. Present Use: | [NÇ] stic, single dwell[01A] |
| x Additions 27. Special Features: None 28. Outbuildings: Non-contributing 29. Original Function: Residential/Domes | [NÇ_] |
| x Additions 27. Special Features: None 28. Outbuildings: Non-contributing 29. Original Function: Residential/Domes 30. Present Use: As above 31. Condition: Fair | [NÇ] stic, single dwell[01A] |
| x Additions 27. Special Features: None 28. Outbuildings: Non-contributing 29. Original Function: Residential/Domes 30. Present Use: As above 31. Condition: Fair | [NC] stic, single dwell[01A] [01A] |
| x Additions 27. Special Features: None 28. Outbuildings: Non-contributing 29. Original Function: Residential/Domes 30. Present Use: As above 31. Condition: | [NÇ] stic, single dwell[01A] [01A] [F] Yes |
| x Additions 27. Special Features: None 28. Outbuildings: Non-contributing 29. Original Function: Residential/Domes 30. Present Use: As above 31. Condition: Fair 32. Endangered: | [NÇ] stic, single dwell[01A] [01A] [F] Yes |
| x Additions 27. Special Features: None 28. Outbuildings: Non-contributing 29. Original Function: Residential/Domes 30. Present Use: As above 31. Condition: Fair 32. Endangered: 33. Attach Photos: | [NÇ] stic, single dwell[01A] [01A] [F] Yes No |
| x Additions 27. Special Features: None 28. Outbuildings: Non-contributing 29. Original Function: Residential/Domes 30. Present Use: As above 31. Condition: Fair 32. Endangered: | [NÇ] stic, single dwell[01A] [01A] [F] Yes No |
| x Additions 27. Special Features: None 28. Outbuildings: Non-contributing 29. Original Function: Residential/Domes 30. Present Use: As above 31. Condition: Fair 32. Endangered: 33. Attach Photos: | [NÇ] stic, single dwell[01A] [01A] [F] Yes No |
| x Additions 27. Special Features: None 28. Outbuildings: Non-contributing 29. Original Function: Residential/Domes 30. Present Use: As above 31. Condition: Fair 32. Endangered: 33. Attach Photos: Roll: Photo No | [NÇ] stic, single dwell[01A] [01A] [F] Yes No S: No. of Slides: |
| x Additions 27. Special Features: None 28. Outbuildings: Non-contributing 29. Original Function: Residential/Domes 30. Present Use: As above 31. Condition: Fair 32. Endangered: 33. Attach Photos: Roll: Photo No | [NÇ] stic, single dwell[01A] [01A] [F] Yes No S: No. of Slides: |
| x Additions 27. Special Features: None 28. Outbuildings: Non-contributing 29. Original Function: Residential/Domes 30. Present Use: As above 31. Condition: Fair 32. Endangered: 33. Attach Photos: Roll: Photo No | [NÇ] stic, single dwell[01A] [01A] [F] Yes No No s: No. of Slides: |

| 34. | Prepared by: C. | Worsham |
|-----|------------------------|----------------------------|
| 35. | Organization: V | , Shelby Co. Hist. Society |
| 36. | Date: April 1 | 986 |
| 37. | New Survey | Resurvey x |


KENTUCKY HISTORIC RESOURCES Individual Inventory Form

| | UTM Point of Primary Building: Quadrant: Shelbyville | Zone 16 | Easting 6 5 7 5 5 0 | Northing <u>4 2 2 9 6 9 0</u> | | G.I.S. Mod. Coordi.Accuracy |] [| | |
|---|---|----------------|-------------------------------|---|---------|--------------------------------|--------|----|--|
| | UTM Points of Boundary (for N. R. eligible sites only): | | | | | | | | |
| | A B. | - | I F |). I | | | | | |
| | C | - - | F | | | · | | | |
| - | Total Acreage in Present Property | : 5.0 | 43. Acre | age included in r | propose | ed N.R. boundary: | . 7 | 71 | |

Site Plan (and boundary description and justification for N.R. sites):

Beginning at A, north 200' along a fence to B, thence east 156' along a fence to C, thence south 200' along a fence to D, thence 156' west along a fence to the point of origin. The boundaries were chosen to include the house and domestic-related space defined by fences on all sides. A non-contributing frame garage is included.

Point A is located at the intersection of two fences in the southwestern corner of the yard and is 13 feet west of the west edge of the drive.



1st. prcht come.fl.

(added?)

elsenhere

will

ferra

Description and House Plan:

Exterior:

3-bay 2-story brick hall-parlor (two-room) plan with early added 1-story two-room lateral wing. South (principal) facade has central door flanked by a door on the east and a window on the west. Whether door on east was a window cannot be determined. Random glazed header Flemish bond front, 6-course common bond elsewhere, 15-course bond on wing. Doors and windows altered, sashes replaced. Jack arches remain, as does panelled reveal at blocked north center door, where former 1-story porch stood. Cellar entry beside chimney at west end.

blocked opening for de

Page 3 of 3 pages

13. Statement of Significance: (continued)

for the latter period, while only one other surviving dwelling pre-dates 1810 (see SH-85). In addition, the house demonstrates the earlier pattern of gaining additional space through lateral expansion as opposed to construction of a rear ell. Despite alterations (window replacement, removal of some woodwork from the interior) which caused loss of detail, the massing and form of the building evoke great integrity of feeling to the early settlement period and remain uncompromised by any additions.

14. History: (continued)

Brackett Owen was the son of John and Phoebe Brackett Owen. He was born in Henrico Co., VA 8/9/1733 and died in Shelbyville in 1802. He married Elizabeth McGehee (b. 1744 - d. 1800). Their son Col. Abraham Owen was killed in the Battle of Tippecance in 1811.

45. Description and House Plan: (continued)

l-story gabled porch on columns shelters two doors. Original box cornice incorporates beaded fascia, quarter round bed mold. Seam in wall both fronts between 1- and 2-story sections.

Interior:

First floor mantels removed; bathroom partitions inserted in both rooms. Ghost of stair in larger room in southwest corner. Beaded-board-enclosed stair in southwest corner of smaller room may have been added. Door bricked up in southwest corner of main section may have been added (?). Second floor incorporates pin rail on south wall of west room, original shelf and architrave mantels. Molded and beaded chairrails and baseboards. First floor moldings include beaded trim with reversed quarter round architrave (see detail) in main section and ovolo in 1-story section. Two-panel doors in interior of main section.

<u>Outbuildings</u>:

There is one non-contributing frame garage included within the boundaries. The nominated area incorporates one contributing and one non-contributing buildings.