

Location: Vicinity of Little Creek, Kent County, Delaware

Photographer: Ned Heite

Date: 1973

Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: looking east; the outbuildings shown in this 1973 photograph no longer survive.

AUG 2 1 1979

Photograph Number: 1 of 9 OCT 2 5 1979



Location: Vicinity of Little Creek, Kent County, Delaware

Photographer: Dean Nelson Date: 1978 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: north elevation

Photograph Number: 2 of 9

PUE

NGT 25 1979


## AUG 2 1 1979



Location: Vicinity of Little Creek, Kent County, Delaware Photographer:Bernard Herman Date:1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: underside of eaves, porch roof and porch outriggers

Photograph Number: 3 of 9

NOE



25



Location: Vicinity of Little Creek, Kent County, Delaware

Photographer: Bernard Herman Date: 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: porch posts, decking and railing

Photograph Number: % 4 of 9

007 25 1979

AUG 2 1 1979




Location: Vicinity of Little Creek, <u>Kent County, Delaware</u> Photographer: Bernard Herman Date: 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: colonial-revival architectural cupboard,

AUG 2 1 1979

and interior woodwork north west room.

Photograph Number:





Port Mahon Lighthouse; K-190 Name:

Location: Vicinity of Little Creek, Kent County, Delaware

Photographer: Bernard Herman Date: 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: colonial revival architectural cupboard and interior woodwork, northwest room

Photograph Number: 6 of 9

00C

AUG 2 1 1979



Location: Vicinity of Little Creek, <u>Kent County, Delaware</u> Photographer: Bernard Herman Date: 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: vertical board wainscoting, chair rail, diagonal board interior wall and door architrate.

0CT 2 5 1979

AUG 2 1 1979

Photograph Number: 7 of 9



Location: Vicinity of Little Creek, Kent County, Delaware

Photographer: Bernard Herman Date: 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: interior woodwork detail, stair pendants.

Photograph Number:

<u>8 of 9</u>

UCT 25 1979

AUG 2 1 1979



Port Mahon Lighthouse; K-190 Name:

Location: Vicinity of Little Creek, Kent County, Delaware Photographer: Bernard Herman Date: 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: interior woodwork detail; vertical board wainscoting, chair rail, diagonal board interior wall.

Photograph Number: <u>9 of 9</u>

AUG 2 1 1970

001 2 5 1979