

Memorial Hall Windsor Locks. CT D. Ransom Photo, 10/86 Negative: Connecticut Historical Commission VIEW SOUTHWEST Photograph 1



Memorial Hall Windsor Locks, CT D. Ransom Photo, 10/86 Negative: Connecticut Historical Commission FRONT ELEVATION. VIEW WEST Photograph 2



Memorial Hall Windsor Locks, CT D. Ransom Photo, 10/86 Negative: Connecticut Historical Commission ENTRANCE, VIEW WEST Photograph 3



Memorial Hall Windsor Locks, CT D. Ransom Photo, 10/86 Negative: Connecticut Historical Commission PLAQUE, VIEW WEST Photograph 4




Memorial Hall Windsor Locks, CT D. Ransom Photo. 10/86 Negagive: Connecticut Historical Commission FRONT GABLE END AND TPWER ROOF, VIEW NORTHWEST Photograph 5



Memorial Hall Windsor Locks, CT D. Ransom Photo, 10/86 Negative: Connecticut Historical Commission VIEW NORTHWEST Photograph 6



Memorial Hall Windsor Locks, CT D. Ransom Photo, 10/86 Negative: Connecticut Historical Commission NORTH ELEVATION, VIEW SOUTHEAST Photograph 7



Memorial Hall Windsor Locks, CT D. Ransom Photo. 10/86 Negative: Connecticut Historical Commission REAR ELEVATION, VIEW SOUTHEAST Photograph 8



Memorial Hall Windsor Locks, CT D. Ransom Photo. 10/86 Negative: Connecticut Historical Commission FIRST-FLOOR TOWER ROOM. VIEW NORTHEAST Photograph 9



Memorial Hall Windsor Locks, CT D. Ransom Photo, 10/86 Negative: Connecticut Historical Commission FIRST-FLOOR TOWER ROOM MANTEL, VIEW SOUTHWEST Photograph 10



Memorial Hall Windsor Locks, CT D. Ransom Photo. 10/86 Negative: Connecticut Historical Commission DOOR. TYPICAL Photograph 11



Memorial Hall Windsor Locks, CT D. Ransom Photo, 10/86 Negative: Connecticut Historical Commission G.A.R. STATIONS Photograph 12



Memorial Hall Windsor Locks, CT D. Ransom Photo, 10/86 Negative: Connecticut Historical Commission AMERICAN LEGION AWARDS AND CERTIFICATES Photograph 13



Memorial Hall Windsor Locks, CT D. Ransom Photo, 10/86 Negative: Connecticut Historical Commission STAIRWAY AT FIRST FLOOR. VIEW SOUTHEAST Photograph 14



Memorial Hall Windsor Locks, CT D. Ransom Photo, 10/86 Negative: Connecticut Historical Commission G.A.R. HALL. VIEW NORTHWEST Photograph 15



Memorial Hall Windsor Locks, CT D. Ransom Photo, 10/86 Negative: Connecticut Historical Commission ATTIC. VIEW WEST Photograph 16



Memorial Hall Windsor Locks. CT D. Ransom Photo, 10/86 Negative: Connecticut Historical Commission TOWER ROOf framing. view northeast Photograph 17