



Name: Seaford Station Complex

Location: Seaford, Delaware

Photographer: Jean Athan

Sussex County

Date: 9/7/77

Location of Negative: Div. of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Hall of Records, Dover, Delaware, 19901.

Description:

View from south of freight station (left) and railroad station (right).

Photograph Number: 1 5 4

NOV 3 1977

S-747

JUN 15 1978



Name: Seaford Railroad Station

Location: Seaford, Delaware

Sussex County

Photographer: Jean Athan

Date: 9/7/77

Location of ~~Negative~~ Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Hall of Records.

Description:

View from northwest.

Photograph Number: 224

NOV 3 1977

JUN 15 1978

S-747



Name: Seaford Freight Station

Location: Seaford, Delaware

Sussex County

Photographer: Jean Athan

Date: 9/7/77

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Hall of Records, Dover, DE 19901

Description:

View of southern section.

Photograph Number: 384

NOV 3 1977

JUN 15 1978

S-747



Name: Seaford Railroad Bridge

Location: Seaford, Delaware

NOV 3 1977

Photographer: Jean Athan

Sussex County

Date: 9/7/77

Location of Negative: Division of Historical & Cultural
Affairs, Bureau of Archaeology & Historic Preservation,
Hall of Records, Dover, Delaware 19901

Description:

View from north of Nanticoke River.

Photograph Number: 4 of 4

S-747

JUN 15 1978