CONTINUATION FROM FRONT SHEET - STRUCTURE NAME HS-	28 Timberline Cabin
OCATION: Section 31 State CO	USE: CURRENT INTERIOR USE (NPS 28 CODE) 00
Township 6N County Larimer	Original Use NPS Quarters
Range75W	Intermediate Uses Same
	PERIOD OF CONSTRUCTION (NPS 28 CODE) HI
OWNERSHIP: Present Owner: U.S. Govt.	DRAWING NO RM 1; RM 3067A; RM 5199
Original Owner: U.S. Govt.	NEGATIVE NO. Roll 17 Negative 64
Intermediate Owner(s): None	
***PHYSICAL D	ESCRIPTION***
TYPE OF STRUCTURE (NPS 28 CODE): BU	CHIMNEYS: One - Of uncoursed fieldstone, on W. elev.,
ARCHITECTURAL CHARACTER (STYLE):	interior.
SITE (INCLUDE ORIENTATION OF STRUCTURE): Open, native tundra. Facade and decline to S.	PORCHES: Four stone and poured concrete steps, on facade.
OVERALL BUILDING PLAN (FOOTPRINT): Rectangular Bays: 5 by 3; Pile: 1 OVERALL DIMENSIONS: 32'4" by 16'4"	WINDOWS: Ten window openings are all boarded over with plywood. Concrete lintels and sills.
COMPOSITION (NPS 28 CODE): ST	
STORIES: One	DOORS: Two - Single, brown, vertical wood boards with interior batts. One on facade, the other on E. elev.
FOUNDATION: Stone walls are level with grade.	
	ADDITIONS: None
WALLS: Concrete with uncoursed fieldstone veneer.	
-	INTERIOR PLAN: Two rooms currently vacant.
ROOF: Gable. Rolled asphalt with exposed ridgepole, plate logs, and closely spaced purlins. Log lattice work on top of rolled asphalt.	INTERIOR FINISHES: Perimeter walls: Concrete. Partition walls: Wood frame. Ceiling: Exposed log frame. Floor: Wood boards.

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT		
(Attach 4" x 5" Black and White Photograph)		
REGION RMR PARK/AREA NAME ROMO PARK NUMBER 1520		
STRUCTURE NAME <u>Timberline Cabin</u> STRUCTURE NUMBER <u>HS-28</u>		
LOCATION OF STRUCTURE Fall River Road PARK LOCATION CODE FP		
Determined Eligible NATIONAL REGISTER SHPO (5) DATE: 8 / /75 MANAGEMENT CATEGORY: (A) (B) 💽 (D)		
NPS LEGAL INTEREST Fee MANAGEMENT AGREEMENT:NO		
Check all of the following categories for which NPS has treatment responsibility:		
Stabilization 🕺 Cyclic Maintenance 🕅 Routine Maintenance 🕅 Approved Ultimate Treatment 🕅		
(ROCKY MOUNTAIN REGION USE ONLY)		
APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:		
Preservation(PP)Restoration(RR)Reconstruction(CC)Adaptive Preservation(AP)Adaptive Restoration(AR)Adaptive Reconstruction(AC)Neglect(NG)Remove(RM)No Approved Treatment(NO)		
Approval Document()Document Date: // Estimated Treatment Costs		
Stabilization:  \$  Date:  / /  Level of    Approved Treatment:  \$  Date:  / /  Estimate:  (A) (B) (C)		
STATEMENT OF SIGNIFICANCE:		
Date of Construction: //1925 Date of Alterations: // Architect/Designer: Landscape Eng.Div.Historical Theme(s): NPS Rustic Architecture History of Structure: Built in 1925. at an estimated cost of \$2,400, Building #28 originally served as quarters for crews working on the Fall River Road. The build- ing also served as a patrol cabin and a caretaker's cabin for the Fall River Road. It currently is vacant. Designs for the structure were prepared by members of the Landscape Engineering Division, Los Angeles Office, under the supervision of T. C. Vint, Assistant Landscape Engineer. Evaluation of Structure: Historic Theme Contributing X_Non-Contributing		
National Register Criteria: $A \not = C \not = D$ (Include integrity statement)		
This stone structure illustrates the development of the "NPS Rustic" style of architecture, and greatly contributes to the historical and architectural		
character of the park. There are no records of any alterations. Bibliography: <u>ROMO Building Maintenance Files. "Supt. Annual Reports.</u>		
<u>1915-1930." National Register Nomination 7/29/75.</u> Representation in Other Surveys: <u>LCS, Lance Williams, 6/28/1976</u>		
If structure has been removed, how? <u>N/A</u> Date: / /		
Report prepared by: <u>Carl and Karen McWilliams</u> Date: <u>8 / 1 /1985</u>		

1.1.4

