



VAMC WOOD, WISCONSIN

WOOD, WISCONSIN

Photographer: Unknown


Date of Photo: Unknown

Negative on File: VA HPO

Ward Memorial Hall, Building 41

Front and side facades

Taken looking northwest



VAMC WOOD, WISCONSIN

WOOD, WISCONSIN

Photographer: Unknown

Date of Photo: 1979

Negative on File: VA HPO

Ward Memorial Hall, Building 41

Front and Side Facades

Taken looking northwest



VAMC WOOD, WISCONSIN

WOOD, WISCONSIN

Photographer: Gjore Mollenhoff

Date of Photo: August, 1978

Negative on File: VA HPO

Ward Memorial Hall, Building 41

Rear elevation, looking south



VAMC WOOD, WISCONSIN

WOOD, WISCONSIN

Photographer: Gjore Mollenhoff

Date of Photo: August, 1978

Negative on File: VA HPO

Ward Memorial Hall, Building 41

Wing with stained glass window
depicting U.S Grant and Horse

Taken looking west at east side



VAMC WOOD, WISCONSIN

WOOD, WISCONSIN

Photographer: Unknown


Date of Photo: Unknown

Negative on File: VA HPO

Ward Memorial Hall, Building 41

East facades of theater

Taken looking southwest



VAMC WOOD, WISCONSIN

WOOD, WISCONSIN

Photographer: Gjore Mollenhoff

Date of Photo: August, 1978

Negative on File: VA HPO

Ward Memorial Hall, Building 41

Interior boxes



VAMC WOOD, WISCONSIN

WOOD, WISCONSIN

Photographer: Gjore Mollenhoff

Date of Photo: August, 1978

Negative on File: VA HPO

Ward Memorial Hall, Building 41

Close up of veranda and front bay

Taken looking southwest



VAMC WOOD, WISCONSIN

WOOD, WISCONSIN

Photographer: Gjore Mollenhoff

Date of Photo: August, 1978

Negative on File: VA HPO

Ward Memorial Hall, Building 41

Original rope and pin system

for flying sets, backdrops, and

scenic curtains



VAMC WOOD, WISCONSIN

WOOD, WISCONSIN

Photographer: Gjore Mollenhoff

Date of Photo: August, 1978

Negative on File: VA HPO

Ward Memorial Hall, Building 41

Close up of windows and brickwork
in front bay



VAMC WOOD, WISCONSIN

WOOD, WISCONSIN

Photographer: Gjore Mollenhoff

Date of Photo: August, 1978

Negative on File: VA HPO

Ward Memorial Hall, Building 41

Wrought iron ornamentation on
top edge of seat backs



VAMC WOOD, WISCONSIN

WOOD, WISCONSIN

Photographer: Gjore Mollenhoff

Date of Photo: August, 1978

Negative on File: VA HPO

Ward Memorial Hall, Building 41

Original wood seats pierced with holes
spelling NSH for National Soldiers Home



VAMC WOOD, WISCONSIN

WOOD, WISCONSIN

Photographer: Gjore Mollenhoff

Date of Photo: August, 1978

Negative on File: VA HPO

Ward Memorial Hall, Building 41

Ornamental plaster columns and
gold leafed cornices near boxes,
stamped metal ceiling