

Levi B. Frost House Southington, CT D. Ransom Photo. 3/87 Negative: Connecticut Historical Commission VIEW NORTHWEST



Levi B. Frost House Southington. CT D. Ransom Photo, 1/87 Negative: Connecticut Historical Commission VIEW SOUTHWEST



Levi B. Frost House Southington, CT D. Ransom Copy, 1/87 Negative: Connecticut Historical Commission HISTORICAL PHOTO. c. 1900? VIEW NORTH

Photogtaph 3



Levi B. Frost House Southington, CT D. Ransom Photo, 3/87 Negative: Connecticut Historical Commission

VIEW SOUTHEAST Photograph 4



Levi B. Frost House Southington. CT D. Ransom Photo, 1/87 Negative: Connecticut Historical Commission

VIEW NORTHEAST Photograph 5



Levi B. Frost House Southington, CT D. Ransom Photo, 1/87 Negative: Connecticut Historical Commission FRONT DOORWAY. VIEW EAST



Levi B. Frost House Southington, CT D. Ransom Photo, 1/87 Negative: Connecticut Historical Commission FRONT CHIMNEY BASE. VIEW


NORTHWEST Photograph 7



Levi B. Frost House Southington, CT D. Ransom Photo. 1/87 Negative: Connecticut Historical Commission FORMER SOUTH DOOR. VIEW SOUTH



Levi B. Frost House Southington, CT D. Ransom Photo. 3/87 Negative: Connecticut Historical Commission TOP OF STAIR. VIEW WEST



Levi B. Frost House Southington, CT D. Ransom Photo, 3/87 Negative: Connecticut Historical Commission REAR BEDROOM, VIEW SOUTH-WEST



Levi B. Frost House Southington, CT D. Ransom Photo, 3/87 Negative: Connecticut Historical Commission SOUTH PURLIN, VIEW SOUTHWEST Photograph 12



Levi B. Frost House Southington, CT D. Ransom Photo. 3/87 Negative: Connecticut Historical Commission BARN. VIEW SOUTHWEST