



Name: St. Hedwig's R.C. Church

Location: Harrison & Linden Sts Wilmington De

Photographer:

Date:

Location of Negative: *estimated 1910* Historical Society of Delaware

Description: Exterior view of church from SW side
of Harrison St.

Photograph Numbers: 1 of 22



Name: St. Hedwig's Roman Catholic Church

Location: Harrison & Linden Sts Wilmington De

Photographer: Patricia A. Maley

Date: Feb 1982

Location of Negative: Wilmington Dept of Planning

Description: Exterior view of front of church
from NE corner of Harrison and Linden Sts.

Photograph Number: 2 of 22



A. D.



1904

Name: St. Hedwig's R.C. Church
Location: Harrison & Linden Sts Wilmington, De
Photographer: Patricia A. Maley
Date: Feb 1982
Location of Negative: Wilmington Dept of Planning
Description: Cornerstone of St. Hedwig's with
date of erection
Photograph Number: 3 of 22



Name: St. Hedwig's R.C. Church

Location: Harrison & Linden Sts Wilmington, De

Photographer: Patricia A. Maley

Date: Feb 1982

Location of Negative: Wilmington Dept of Planning

Description: Detail of spire

Photograph Number: 4 of 22



Name: St. Hedwig's Church

Location: Harrison & Linden Sts W Ilmington, Del

Photographer: Patricia A. Maley

Date: Feb 1982

Location of Negative: Wilmington Dept of Planning

Description: Exterior detail- front doorway facing
Harrison Street (main entrance)

Photograph Numbers: S F 22



Name: St. Hedwig's Roman Catholic Church

Location: Harrison & Linden Sts, Wilmington, Del

Photographer: Patricia A. Maley

Date: Feb 1982

Location of Negative: Wilmington Dept of Planning

Description: Exterior detail- window with tracery
brick corbelling

Photograph Number: 6 of 22



Name: St. Hedwig's R.C. Church

Location: Harrison & Linden Sts, Wilmington, De

Photographer: Patricia A. Maley

Date: January 1982

Location of Negative: Wilmington Dept of Planning

Description: Rear/side view of church, showing outer view of rose window, brick corbelling, quatrefoil design on rear windows.

Photograph Number: 7 of 22



Name: St. Hedwig's Roman Catholic Church

Location: Harrison & Linden Sts. Wilmington, De

Photographer: Patricia A. Maley

Date: Feb 1982

Location of Negative: Wilmington Dept of Planning

Description: View of Altar up the main aisle
from rear of Church

Photograph Number: 8 of 22



Name: St. Hedwig's R.C. Church

Location: Harrison & Linden Sts, Wilmington, De

Photographers: Patricia A. Maley

Date: Feb 1982

Location of Negative: Wilmington Dept of Planning

Description: Interior-view of balcony/choir loft
organ, and rear of Church from sanctuary

Photograph Number: 9 of 22



Name: St. Hedwig's R.C. Church

Location: Harrison & Linden St Wilmington, Delaware

Photographers: Patricia A. Maley

Date: Feb 1982

Location of Negatives: Wilmington Dept of Planning

Description: Interior - Main Altar and Tabernacle

Photograph Numbers: 10 of 22



Name: St Hedwig's R.C. Church

Location: Harrison & Linden Sts Wilmington, Delaware

Photographer: Patricia A. Maley

Date: Feb 1982

Location of Negative: Wilmington Dept of Planning

Description: Interior detail-pulpit

Photograph Numbers: 11 & 22



Name: St. Hedwig's R.C. Church

Location: Harrison & Linden Sts Wilmington, De

Photographers: Patricia A. Maley

Date: Feb 1982

Location of Negative: Wilmington Dept of Planning

Description: Interior detail-showing vaulting of nave and rear balcony

Photograph Numbers: 12 of 22



Name: St Hedwig's R.C. Church

Location: Harrison & Linden STS Wilmington, Delaware


Photographer: Patricia A. Maley

Date: Feb 1982

Location of Negative: Wilmington Dept of Planning

Description: Rose window/stained glass over confessionals

Photograph Numbers: 13 of 22



Name: St. Hedwig's R.C. Church

Location: Harrison & Linden Sts Wilmington, Delaware

Photographer: Patricia A. Maley

Date: Feb 1982

Location of Negative: Wilmington Dept of Planning

Description: Interior- Rose Window/stained glass

Photograph Number: 14 of 22



Name: St, Hedwig's Roman Catholic Church

Location: Harrison and Linden Sts Wilmington, Delawa

Photographer: Patricia A. Maley

Date: Feb 1982

Location of Negative: Wilmington Dept of Planning

Description: Interior Ceiling detail in apse

Photograph Number:

15 & 22



Name: St. Hedwig's Roman Catholic Church
Location: Harrison & Linden Sts W Wilmington De


Photographers: Patricia A. Maley

Date: Feb 1982

Location of Negatives: Wilmington Dept of Planning

Description: Interior Detail-orient in ceiling
featuring Sts. Mathew, Mark, Luke and John

Photograph Numbers 16 & 22



Name: St. Hedwig's R.C. Church

Location: Harrison & Linden Sts. Wilmington, De

Photographer: Patricia A. Maley

Date: Feb 1982

Location of Negatives: Wilmington Dept of Planning

Description: Interior-detail of newell post and wainscoting and window in the vestibule

Photograph Number: 17 of 22



Name: St. Hedwig's R.C. Church

Location: Harrison & Linden STS Wilmington, DE

Photographer:

Date: Feb '82 Patricia A. Maley

Location of Negative: Wilmington dept of Planning

Description: Interior Detail-stained glass window with carved representations of Stations of the Cross. Also shows lamp and vaulting detail.

Photograph Number: 18 of 22



Name: St Hedwig's Church

Location: Harrison & Linden Sts Wilmington, Delaware


Photographers: Patricia A. Maley

Date: Feb 1982

Location of Negatives: Wilmington Dept of Planning

Description: Interior detail-compound arch doorway
with inset stained glass detailing

Photograph Numbers: 19 of 22



Name: St Hedwig's Roman Catholic Church

Location: Harrison & Linden Sts Wilmington, Delaware

Photographer: Patricia A. Maley

Date: Feb 1982

Location of Negative: Wilmington Dept of Planning

Description: Interior detail-side altar

Photograph Numbers

20 & 22



Name: St. Hedwig's R.C. Church

Location: Linden & Harrisno STS Wilmington, Delaware

Photographer: Patricia A. Maley

Date: Feb 1982

Location of Negative: Wilmington Dept of Planning

Description: Interior Detail- gate to side altar
detail work in wrought iron, sides in color tile

Photograph Number: 21 of 22



Name: St Hedwig's Roman Catholic Church

Location: Harrison and Linden St. Wilmington De

Photographer: Patricia A. Maley

Date: Feb 1982

Location of Negative: Wilmington Dept of Planning

Description: Interior Detail-Column

Photograph Numbers:

22 of 22