



STEP  
HOME

William Stevens House

Clinton, CT

D. Ransom Photo, 8/84

Negative: Connecticut  
Historical Commission

FRONT ELEVATION, VIEW

NORTHWEST

Photograph 1



William Stevens House  
Clinton, CT  
D. Ransom Photo, 8/84  
Negative: Connecticut  
Historical Commission  
NORTH ELEVATION, VIEW  
SOUTH  
Photograph 2



William Stevens House  
Clinton, CT  
D. Ransom Photo, 8/84  
Negative: Connecticut  
Historical Commission  
SOUTH ELEVATION, VIEW  
NORTHEAST  
Photograph 3





William Stevens House  
Clinton, CT

D. Ransom Photo, 8/84

Negative: Connecticut  
Historical Commission

WEST ELEVATION, VIEW EAST

Photograph 4





William Stevens House  
Clinton, CT  
D. Ransom Photo, 8/84  
Negative: Connecticut  
Historical Commission  
GENERAL VIEW SOUTHWEST  
Photograph 5



William Stevens House  
Clinton, CT  
D. Ransom Photo, 8/84  
Negative: Connecticut  
Historical Commission  
GENERAL VIEW NORTHEAST  
Photograph 6



William Stevens House

Clinton, CT

D. Ransom Photo, 8/84

Negative: Connecticut

Historical Commission

HAY BARN, VIEW NORTHWEST

Photograph 7





William Stevens House  
Clinton, CT  
D. Ransom Photo, 8/84  
Negative: Connecticut  
Historical Commission  
STAIRWAY, VIEW SOUTHEAST  
Photograph '8




William Stevens House  
Clinton, CT

D. Ransom Photo, 8/84  
Negative: Connecticut  
Historical Commission

LIVING ROOM, VIEW NORTH-  
WEST

Photograph 9



William Stevens House  
Clinton, CT

D. Ransom Photo, 8/84

Negative: Connecticut  
Historical Commission

CHIMNEY STACK, VIEW

NORTHEAST

Photograph 10





William Stevens House  
Clinton, CT  
D. Ransom Photo, 8/84  
Negative: Connecticut  
Historical Commission  
KITCHEN FIREPLACE, VIEW  
EAST  
Photograph 11



William Stevens House  
Clinton, CT

D. Ransom Photo, 8/84

Negative: Connecticut  
Historical Commission

CEILING BEHIND CHIMNEY,  
VIEW NORTHWEST

Photograph 12



William Stevens House

Clinton, CT

D. Ransom Photo, 8/84

Negative: Connecticut

Historical Commission

NOTCH IN TIMBER, VIEW

NORTHEAST

Photograph 13





William Stevens House  
Clinton, CT

D. Ransom Photo, 8/84

Negative: Connecticut  
Historical Commission

CHIMNEY STACK BASE, VIEW  
NORTHWEST

Photograph 14



William Stevens House  
Clinton, CT  
D. Ransom Photo, 8/84  
Negative: Connecticut  
Historical Commission  
SECOND FLOOR, SOUTH FRONT  
ROOM, VIEW SOUTHWEST  
Photograph 15





William Stevens House  
Clinton, CT  
D. Ransom Photo, 8/84  
Negative: Connecticut  
Historical Commission  
SECOND FLOOR, CHIMNEY STACK,  
VIEW EAST  
Photograph 16