

A black and white photograph of the Claremont Hotel train station in California. The building features a prominent, ornate arched entranceway supported by two columns, with intricate carvings above it. The main structure is a single-story building with a tiled roof and several arched windows and doors. The word "CLAREMONT" is painted in large, bold letters across the side of the building. In the foreground, there are railroad tracks and some dry, scrubby vegetation.

CLAREMONT

A.T. and S.F. R.R. Station 110 W. First St.
Claremont, Los Angeles County, CA
Claremont Historic Resources Center
1980

Claremont Historic Resources Center
south elevation of depot
view to the NW

1 of 10



CLAREMONT

A.T. and S.F. R.R. Station 110 W. First St.
Claremont, Los Angeles County, CA
Claremont Historic Resources Center
1980

Claremont Historic Resources Center
north elevation of depot
view to the SE

A black and white photograph of the Claremont Hotel, a large, ornate building with a tiled roof and arched windows. A prominent feature is a decorative arched entranceway on the left side. The word "CLAREMONT" is painted in large letters on the side of the building. In the foreground, there are train tracks and some trees. The sky is overcast.

CLAREMONT

A.T. and S.F. R.R. Station 110 W. First St.
Claremont, Los Angeles County, CA
Claremont Historic Resources Center
1979

Claremont Historic Resources Center
south elevation of dépôt
view to the NW



A.T. and S.F. R.R. Station 110 W. First St.

Claremont, Los Angeles County, CA

Claremont Historic Resources Center

1979

Claremont Historic Resources Center

Claremont Historic Resources Center

east elevation of depot

view to the W

4 of 10



CLAREMONT

A.T. and S.F. R.R. Station 110 W. First St.

Claremont, Los Angeles County, CA

Claremont Historic Resources Center


1979

Claremont Historic Resources Center

north elevation

view to the SE

5 of 10



A black and white photograph of the Claremont Hotel entrance. The building is a single-story structure with a light-colored, possibly stucco, exterior. It features a prominent arched entranceway on the left and a smaller arched opening to the right. Above the arched entrance, the word "CLAREMONT" is written in large, bold, capital letters. The roofline is decorated with dark, scalloped tiles. To the right of the main entrance, there is a tall, ornate columned structure, likely a porte-cochere or a separate entrance. The background shows some trees and a clear sky. The image has a slightly grainy texture and some minor surface marks.

CLAREMONT

A.T. and S.F. R.R. Station 110 W. First St.
Claremont, Los Angeles County, CA
Claremont Historic Resources Center
1979

Claremont Historic Resources Center
west elevation with waiting area
view to the E

6 of 10



A.T. and S.F. R.R. Station 110 W. First St.

Claremont, Los Angeles County, CA

Claremont Historic Resources Center

1979

Claremont Historic Resources Center

north elevation camera facing S.W.

view to the SW

7 of 10



A.T. and S.F. R.R. Station 110 W. First St.
Claremont, Los Angeles County, CA
Claremont Historic Resources Center


1979

Claremont Historic Resources Center

south elevation arched windows

view to the N

8 of 10



A.T. and S.F. R.R. Station 110 W. First St.
Claremont, Los Angeles County, CA
Claremont Historic Resources Center
1979

Claremont Historic Resources Center
South elevation - churrigueresque decoration
view to the N.



A.T. and S.F. R.R. Station 110 W. First St.
Claremont, Los Angeles County, CA
Claremont Historic Resources Center

1979

Claremont Historic Resources Center
South elevation - churrigueresque decoration
view to the NW

10 of 10